

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007524/T1PS3Q2
Date: 15/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100498458
Claimant Vehicle No :	SHC2546T	Insured Vehicle No :	SBX113H
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	7137166149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2546T		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2B83387
Reg. Date:	06/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU403077662
Colour:	Blue	Odometer:	309065 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,995.20	1,023.72	971.48	48.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,645.00	725.00	30.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,365.20	2,668.72	1,696.48	38.86
+ GST 7.00/7.00% (S\$)	305.56	186.81	118.75	38.86

Nett Amount (S\$)	4,670.76	2,855.53	1,815.23	38.86
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$126.47/day) (S\$)		505.88		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,563.41		
Global Sum Settlement (S\$)		3,560.00		

INSPECTION

Date of Assignment: 12/07/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY RR DOOR RH	Bent	1,258.30 FL	*1,258.30 FL
2	1		*PANEL SUB -ASSY QUARTER RH	Repair	836.70 FL	*- FL
3	1		*COVER REAR BUMPER	Repair	458.60 FL	*- FL
4	1		*APP LOGO REAR DOOR L/R CT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,633.60	1,338.30
- List Item Discount on L Items 25.00/25.00% (\$)	638.40	314.58
Total Parts (\$)	1,995.20	1,023.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,100.00	525.00
2	SPRAYPAINT CHARGE	New	800.00	750.00
3	REMOVE/REFIX UPHOLSTERY ASSY REPAIR	New	100.00	60.00
4	TRANSFER DOOR PART	New	120.00	60.00
5	RENEW ADVERTISEMENT STICKER	New	200.00	200.00
6	RENEW ADVERTISEMENT STICKER -BUMPER	New	50.00	50.00
Gross Labour Cost (S\$)			2,370.00	1,645.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >