

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007525/AQCN2**Date:** 24/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00003642100		
<b>Claimant Vehicle No :</b>	GBJ4005J	<b>Insured Vehicle No :</b>	YP3434G		
Date of Loss:	09/07/2021	Nature of Claim:	TP	Claim No:	SNM21D203833/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBJ4005J</b>	Engine No:	1GD8375646
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012004698
Reg. Date:	12/04/2019 (Man. Year: 2019)	Odometer:	89431 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,638.15	3,636.52	1,001.63	21.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,240.00	720.00	36.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,598.15</b>	<b>4,876.52</b>	<b>1,721.63</b>	<b>26.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,900.00</b>		
<b>(S\$)</b>	6,598.15	3,900.00	2,698.15	40.89
<b>+ GST 7.00/7.00% (S\$)</b>	461.87	273.00	188.87	40.89
<b>Nett Amount (S\$)</b>	<b>7,060.02</b>	<b>4,173.00</b>	<b>2,887.02</b>	<b>40.89</b>

**INSPECTION**

Date of Assignment:	12/07/2021	
Date Inspected:	12/07/2021 Inspected At:	N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ) KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18 Singapore 417921
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2022)
<b>Parts:</b> 213	TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for GBJ4005J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	430.90 FL	*- FL
2	1		*REAR RH TAILLAMP	Cut	354.80 FL	*354.80 FL
3	1		*REAR RH TAILLAMP LOWER GARNISH	Not Necessary	157.00 FL	*- FL
4	1		*REAR TAILGATE	Dented	2,162.70 FL	*2,162.70 FL
5	1		*REAR TAILGATE LOGO EMBLEM	Necessary	71.60 FL	*71.60 FL
6	1		*REAR TAILGATE HIACE STICKER EMBLEM	Necessary	58.00 FL	*58.00 FL
7	1		*REAR TAILGATE INNER TRIM BOARD COVER	Not Necessary	181.00 FL	*- FL
8	2		*REAR TAILGATE LOWER CLUST SEAL COVER L/R	Not Necessary	23.40 FL	*- FL
9	2		*REAR TAILGATE LOWER JOINT SEAL COVER L/R	Not Necessary	23.20 FL	*- FL
10	1		*REAR TAILGATE OUTER GARNISH	Cut	261.60 FL	*261.60 FL
11	1		*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,340.00 FL	*1,340.00 FL
12	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
13	1		*SET REAR RH TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
14	1		*REAR TAILGATE 1200KG STICKER	Necessary	50.00 FS	*30.00 FS
15	1		*REAR TAILGATE 6PAX STICKER	Necessary	25.00 FS	*15.00 FS
16	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
17	1		*SET REAR TAILGATE INNER TRIM BOARD COVER CLIPS	Not Necessary	50.00 FS	*- FS
18	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
19	1		*REAR TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	80.00 FS	*40.00 FS
20	1		*REAR TAILGATE WINDSCREEN GLASS SOLAR FILM	Necessary	450.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,904.20</b>	<b>4,698.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,266.05	1,062.18
<b>Total Parts (\$\$)</b>	<b>4,638.15</b>	<b>3,636.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	30.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	100.00	0.00
4	TO SEND VEHICLE FOR CLEANING,SHAMPOO,UPHOLSTERY AND CUSHION SEAT	New	120.00	80.00
5	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	500.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	400.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	30.00
8	TO REMOVE N REFIX REAR GATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,960.00</b>	<b>1,240.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**