



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HUI YANG MOTOR PTE LTD BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARESINGAPORE 575721 ON BEHALF OF TAY-JIXIANG			Ref: CS/TP21007526/Kqce2 Date: 22/07/2021 Code: TP034	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SKR 3947Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	05/07/2021	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER (A)	c.c	1986
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	ZSU600028325	Colour	METALLIC BLACK
	Odometer	232077 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	CONTINENTAL	7 mm
	L/H Front Tyre	235/60 R18	CONTINENTAL	7 mm
	R/H Rear Tyre	235/60 R18	CONTINENTAL	7 mm
	L/H Rear Tyre	235/60 R18	CONTINENTAL	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/06/2021	Inspection Date	05/07/2021
	Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	