

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007535/KPA3Q2

Date: 19/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700025333
Claimant Vehicle No :	SMX8579P	Insured Vehicle No :	GBG2854D
Date of Loss:	09/07/2021	Nature of Claim:	TP
		Claim No:	1018111409SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8579P	Engine No:	1NZR804147
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707179638
Reg. Date:	01/02/2021 (Man. Year: 2019)	Odometer:	20802 km
Colour:	Metallic Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,391.50	3,312.80	6,078.70	64.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,910.00	1,820.00	48.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,121.50	5,222.80	7,898.70	60.20
Approved Total (Overridden) (S\$)		4,150.00		
(S\$)	13,121.50	4,150.00	8,971.50	68.37
+ GST 7.00/7.00% (S\$)	918.51	290.50	628.01	68.37
Nett Amount (S\$)	14,040.01	4,440.50	9,599.51	68.37
+ Loss of Use (8.0 x S\$64.00/day) (S\$)		512.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,954.50		

INSPECTION

Date of Assignment:	12/07/2021	
Date Inspected:	13/07/2021	Inspected At: Ding Auto Pte Ltd (HQ) 176 Sin Ming Drive #04-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,131.90 FL	*1,131.90 FL
2	1		*REAR BOOTLID GARNISH	Warped	207.90 FL	*207.90 FL
3	1		*REAR BOOTLID DAMPER ABSORBER RHS	Serviceable	242.50 FL	*- FL
4	1		*REAR BOOTLID DAMPER ABSORBER LHS	Serviceable	242.50 FL	*- FL
5	1		*REAR BOOTLID INSULATOR	Serviceable	138.00 FL	*- FL
6	1		*REAR BOOTLID LOCK ASSY CPL	Dented	467.60 FL	*318.67 FL
7	1		*REAR BOOTLID RUBBER SEAL	Cut	372.30 FL	*372.30 FL
8	1		*REAR OUTER TAILLAMP RHS	Serviceable	358.80 FL	*- FL
9	1		*REAR OUTER TAILLAMP LHS	Serviceable	358.80 FL	*- FL
10	1		*REAR INNER LAMP RHS	Serviceable	190.90 FL	*- FL
11	1		*REAR INNER LAMP LHS	Serviceable	190.90 FL	*- FL
12	1		*REAR BOOTLID BADGE	Necessary	67.50 FL	*67.50 FL
13	1		*REAR BUMPER	Mtg Cracked	408.70 FL	*408.70 FL
14	1		*REAR BUMPER UPPER GARNISH	Buckled	190.00 FL	*190.00 FL
15	1		*REAR BUMPER SUPPORT PANEL	No such part	433.60 FL	*- FL
16	3		*REAR BUMPER GARNISH (R/L/CTR)	Serviceable	449.40 FL	*- FL
17	1		*REAR BUMPER REFLECTOR RHS	Serviceable	191.00 FL	*- FL
18	1		*REAR BUMPER REFLECTOR LHS	Serviceable	191.00 FL	*- FL
19	1		*REAR BUMPER TOWING CAP	Serviceable	23.00 FL	*- FL
20	1		*REAR BUMPER RETAINER RHS	Serviceable	75.50 FL	*- FL
21	1		*REAR BUMPER RETAINER LHS	Serviceable	75.50 FL	*- FL
22	1		*REAR END PANEL	Bent	696.30 FL	*633.60 FL
23	1		*REAR WIPER LINKAGE	Serviceable	94.00 FL	*- FL
24	1		*REAR WIPER MOTOR	Serviceable	675.70 FL	*- FL
25	1		*REAR WIPER ARM	Serviceable	42.60 FL	*- FL
26	1		*REAR BUMPER HARDNESS WIRE CPL	Serviceable	476.70 FL	*- FL
27	1		*REAR BOOTLID SENSOR (END-PANEL)	Cracked	107.00 FL	*107.00 FL
28	1		*REAR EXHAUST TAIL PIPE (END)	Repair	805.40 FL	*- FL
29	1		*REAR BOOTLID INNER SHIELD	Serviceable	77.70 FL	*- FL
30	1		*BATTERY COVER	Distorted	185.50 FL	*185.50 FL
31	1		*BATTERY GARNISH	Deformed	293.50 FL	*293.50 FL
32	1		*BATTERY BRACKET CPL	Repair	85.30 FL	*- FL
33	1		*BATTERY TRAY	Repair	52.80 FL	*- FL
34	1		*REAR WINDSCREEN	Serviceable	1,181.70 FL	*- FL
35	1		*REAR WINDSCREEN MOULDING	Necessary	180.50 FL	*180.50 FL
36	1		*REAR BUMPER AND MUD GUARD CLIP /BRACKET	Serviceable	100.00 FS	*- FS
37	1		*REAR REVERSE CAMERA ASSY	Serviceable	300.00 FS	*- FS
38	1		*REAR REVERSE SENSOR ASSY	Scratched	350.00 FS	*200.00 FS
39	1		*REAR WINDSCREEN TINTED	Not Necessary	300.00 FS	*- FS
40	1		*WINDSCREEN PRIMER AND SEALANT	Necessary	80.00 FS	*40.00 FS
41	1		*NUMBER PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,132.00	4,337.07
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,740.50	1,024.27
Total Parts (\$\$)	9,391.50	3,312.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	New	1,000.00	850.00
2	STRAIGHTEN AND ALIGN REAR BOOT PLATFORM/REAR CHASSIS	New	550.00	0.00
3	SPRAY PAINT -REAR BUMPER ,FENDER LHS ,END PANEL ,SPARE TYRE BOOTH ,BOOTLID (OUTER & INNER)	New	1,500.00	800.00
4	REMOVE AND REFIT REAR BUMPER ,REAR BOOTLID COMPONENTS	New	150.00	60.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	REMOVE AND REPAIR EXHAUST SYSTEM	New	180.00	0.00
7	ALIGN AND TEST REVERSE CAMERA ,REVERSE SENSOR AND BOOTLID SENSOR WIRING	New	150.00	60.00
8	ALIGN AND TEST TAIL LAMP WIRING	New	50.00	20.00
Gross Labour Cost (\$)			3,730.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >