3/8/23, 1:06 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007544/KPA3Q2

G4FGBU309110

Date: 08/03/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100359705

Claimant Vehicle SKD5386C Insured Vehicle No: SKL8820D

No: Skidosoft insured vehicle No. Skidosoft

Date of Loss: 09/07/2021 Nature of Claim: TP Claim No: 3069983064SG

Engine No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD5386C

Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR

e & iviodei. (A)

1591 cc

Reg. Date: 13/12/2011 (Man. Year: 2011) Chassis No: KMHDH41CMCU251728

Colour: Metallic Black Odometer: 182101 km

Engine Capacity:
Market Value/New Car

r N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,692.00	555.52	1,136.48	67.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	650.00	400.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,742.00	1,205.52	1,536.48	56.04
Approved Total (Overridden) (S\$)		950.00		
(S\$)	2,742.00	950.00	1,792.00	65.35
+ GST 7.00/7.00% (S\$)	191.94	66.50	125.44	65.35
Nett Amount (S\$)	2,933.94	1,016.50	1,917.44	65.35
+ Loss of Use (3.0	x S\$60.00/day) (S\$)	180.00		
	(S\$)	1,196.50		
Liable An	nount (50.00%) (S\$)	598.25		
+ D	oc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	605.70		
Global S	um Settlement (S\$)	600.00		

INSPECTION

Date of Assignment: 12/07/2021

Wei Lee Motor Works (HQ)
Date Inspected: 30/07/2021 Inspected At: BLOCK 9 SIN MING INDUS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32

Singapore 575644

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Serviceable	763.60 FL	*- FL
2	1		*FRONT BUMPER	Mtg Cracked	474.40 FL	*474.40 FL
3	1		*FRONT FENDER	Repair	547.20 FL	*- FL
4	1		*FENDER COWLING	Serviceable	67.80 FL	*- FL
5	1		*COWLING CLIP	Not Necessary	42.00 FL	*- FL
6	1		*RIM FRONT LH	Dented	220.00 FL	*220.00 FL
F=Fra	ınchise	part. L=ListItemDis	sc.			
				Sub Total (S\$)	2,115.00	694.40
- List Item Discount on L Items 20.00/20.00% (S\$)				423.00	138.88	
				Total Parts (S\$)	1,692.00	555.52
			Report was unsu	bmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR /RESHAPE DENTED AREAS REPLACE /ALIGN ABOVE PARTS INTO POSITION	New	550.00	250.00		
2	TO SPRAY PAINT	New	500.00	400.00		
	Gross Labo	ur Cost (S\$)	1,050.00	650.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >