

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007546/T1GS3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070112047
Claimant Vehicle No :	SHD1623E	Insured Vehicle No :	SMU630S
Date of Loss:	11/07/2021	Nature of Claim:	TP
		Claim No:	6727348501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1623E	Engine No:	G4LEJU154737
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU129534
Reg. Date:	24/01/2019 (Man. Year: 2018)	Odometer:	159813 km
Colour:	Silver		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,056.56	3,219.24	837.32	20.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,630.00	880.00	35.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,566.56	4,849.24	1,717.32	26.15
Approved Total (Overridden) (S\$)		3,800.00		

(S\$)	6,566.56	3,800.00	2,766.56	42.13
+ GST 7.00/7.00% (S\$)	459.66	266.00	193.66	42.13
Nett Amount (S\$)	7,026.22	4,066.00	2,960.22	42.13
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$64.20/day) (S\$)		256.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,524.80		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 12/07/2021

Date Inspected: 12/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,480.40 FL	*2,480.40 FL
2	1		*TAILGATE LOCK	Not Necessary	24.80 FL	*- FL
3	1		*EMBLEM HYUNDAI	Necessary	28.00 FL	*28.00 FL
4	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
5	1		*EMBLEM LONIQ	Necessary	31.30 FL	*31.30 FL
6	1		*ANTENNA ASSY -SMART KEY	Not Necessary	41.90 FL	*- FL
7	1		*LAMP ASSY -REAR FOG	Cracked	201.50 FL	*201.50 FL
8	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
9	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
10	2		*REAR BUMPER REINFORCEMENT N/S & O/S LOWER BRACKET	Bent	20.00 FL	*20.00 FL
11	1		*REAR BUMPER REINFORCEMENT CENTRE LOWER BRACKET	Bent	15.00 FL	*15.00 FL
12	2		*REAR BUMPER N/S & O/S STAY	Not Necessary	276.20 FL	*- FL
13	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Not Necessary	66.20 FL	*- FL
14	1		*REAR BUMPER LOWER MOULDING CENTRE	Deformed	216.50 FL	*216.50 FL
15	1		*REAR BUMPER LOWER COVER	Not Necessary	47.50 FL	*- FL
16	1		*REAR BUMPER CAP HOOK	Cut	9.10 FL	*9.10 FL
17	2		*REAR BUMPER N/S & O/S REFLECTOR	Not Necessary	63.80 FL	*- FL
18	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
19	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
20	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*45.00 FS
21	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*80.00 FS
22	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	38.00 FS	*- FS
23	1		*SET SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,916.70	3,975.30
- List Item Discount on L Items 20.00/20.00% (\$)	860.14	756.06
Total Parts (\$)	4,056.56	3,219.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS ONTO NEW TAILGATE	New	120.00	120.00
3	TO DISMANTLE /REFIT REAR TAILGATE WINDOW GLASS ONTO NEW TAILGATE	New	120.00	60.00
4	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
5	TO DISMANTLE /REFIT THE GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT, CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	60.00
6	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	1,000.00	600.00
7	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL,REAR BUMPER LOWER COVER (BLACK) TAILGATE	New	800.00	700.00
8	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	30.00
Gross Labour Cost (S\$)			2,510.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >