



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
EDWIN HO YANHUI	Cust No/Name	LCV13941/EDWIN HO YANHUI
BLK 805C KEAT HONG CLOSE	Reg No/Reg Date	SMY6524E / 19/03/202
#14-66	Date In/Mileage	/ 0
SINGAPORE 683805	Chassis No	MZBER811VLN124683
Contact No	Engine No	G4LDLD032978
	Make/Model	KIA/SELTO 1.4 A SX SR G605
	Colour/Trim	A7A PUNCHY ORANGE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13941	CRDVCH	12/07/2021/ 15:13		442 / CocoLu	35939			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT PANEL								
E PNT98000								2400.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT PANEL								
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								80.00
TOP UP AIRCON GAS								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
A 90000001								250.00
RENEW INTER COOLER								
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M	COVER-FR BUMPER UPR				1.00	229.00	00.00	229.00
M	GRILLE-FRONT BUMPER				1.00	78.00	00.00	78.00
M	COVER-FR BUMPER,LWR				1.00	229.00	00.00	229.00
M	SKID PLATE-FR BUMPER				1.00	57.00	00.00	57.00
M	COVER-FR FOG LAMP LWR,RH				1.00	121.00	00.00	121.00
M	COVER-FR FOG LAMP LWR,LH				1.00	121.00	00.00	121.00
M	WIRING HARNESS-FR BUMPER				1.00	191.00	00.00	191.00
M	GARNISH-RADIATOR GRILLE				1.00	433.00	00.00	433.00
M	COVER-RADIATOR GRILLE UPR				1.00	62.00	00.00	62.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
EDWIN HO YANHUI  BLK 805C KEAT HONG CLOSE #14-66 SINGAPORE 683805  <b>Contact No</b>	Cust No/Name	LCV13941/EDWIN HO YANHUI
	Reg No/Reg Date	SMY6524E / 19/03/202
	Date In/Mileage	/ 0
	Chassis No	MZBER811VLN124683
	Engine No	G4LDLD032978
	Make/Model	KIA/SELTO 1.4 A SX SR G605
	Colour/Trim	A7A PUNCHY ORANGE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV13941	CRDVCH	12/07/2021/ 15:13		442 / CocoLu	35939
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	GRILLE ASSY-RADIATOR,LWR	1.00	68.00	00.00	68.00
M	PIECE-RADIATOR GRILLE NO.2	1.00	448.00	00.00	448.00
M	GRILLE-RADIATOR	1.00	332.00	00.00	332.00
M	ABSORBER-FRONT BUMPER ENERGY	1.00	90.00	00.00	90.00
M	BRACKET-FR BUMPER SIDE,LH	1.00	8.00	00.00	8.00
M	BRACKET-FR BUMPER SIDE,RH	1.00	8.00	00.00	8.00
M	ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	00.00	163.00
M	PAD-HOOD INSULATING	1.00	108.00	00.00	108.00
M	ROD ASSY-HOOD STAY	1.00	30.00	00.00	30.00
M	LATCH ASSY-HOOD	1.00	119.00	00.00	119.00
M	PANEL ASSY-HOOD	1.00	1073.00	00.00	1073.00
M	HINGE ASSY-HOOD,LH	1.00	53.00	00.00	53.00
M	HINGE ASSY-HOOD,RH	1.00	53.00	00.00	53.00
M	PANEL-FENDER,RH	1.00	392.00	00.00	392.00
M	PANEL-FENDER,LH	1.00	392.00	00.00	392.00
M	MEMBER ASSY-RADIATOR SUPT,UPR	1.00	179.00	00.00	179.00
M	BEAM COMPLETE-FR BUMPER	1.00	364.00	00.00	364.00
M	BRACKET ASSY-FENDER & BPR MTG,RH	1.00	9.00	00.00	9.00
M	EMBLEM-SYMBOL MARK KIA	1.00	43.00	00.00	43.00
M	LAMP ASSY-HEAD,LH	1.00	3547.00	00.00	3547.00
M	LAMP ASSY-HEAD,RH	1.00	3547.00	00.00	3547.00
M	PROTECTOR-WIRING	1.00	15.00	00.00	15.00
M	HORN ASSY-LOW PITCH	1.00	58.00	00.00	58.00
M	RESERVOIR & PUMP ASSY-WASHER	1.00	103.00	00.00	103.00
M	STRIP ASSY FR-HOOD	1.00	19.00	00.00	19.00
M	WIRING ASSY-FRT	1.00	4881.00	00.00	4881.00
M	WIRING ASSY-BATTERY	1.00	543.00	00.00	543.00
M	BUZZER ASSY-PIEZO	1.00	58.00	00.00	58.00
M	SENSOR ASSY-A TYPE CRASH	1.00	54.00	00.00	54.00
M	GUARD-AIR	1.00	140.00	00.00	140.00
M	PIPE & TUBE ASSY	1.00	169.00	00.00	169.00
M	CONDENSER ASSY-COOLER	1.00	639.00	00.00	639.00
M	INSULATOR-RADIATOR MTG,LWR	1.00	7.00	00.00	7.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
EDWIN HO YANHUI	Cust No/Name LCV13941/EDWIN HO YANHUI
BLK 805C KEAT HONG CLOSE	Reg No/Reg Date SMY6524E / 19/03/202
#14-66	Date In/Mileage / 0
SINGAPORE 683805	Chassis No MZBER811VLN124683
Contact No	Engine No G4LDLD032978
	Make/Model KIA/SELTO 1.4 A SX SR G605
	Colour/Trim A7A PUNCHY ORANGE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV13941	CRDVCH	12/07/2021/ 15:13		442 / CocoLu	35939
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET ASSY-RADIATOR MTG,UPR		1.00	18.00	00.00	18.00
M BRACKET ASSY-RADIATOR MTG,UPR		1.00	18.00	00.00	18.00
M RADIATOR ASSY		1.00	462.00	00.00	462.00
M HOSE ASSY-WATER		1.00	63.00	00.00	63.00
M HOSE-RADIATOR TO RESERVOIR		1.00	33.00	00.00	33.00
M HOSE ASSY-RADIATOR,UPR		1.00	51.00	00.00	51.00
M FILLER NECK & HOSE ASSY-RAD		1.00	86.00	00.00	86.00
M BLOWER ASSY		1.00	574.00	00.00	574.00
M AIR GUIDE-INTERCOOLER		1.00	52.00	00.00	52.00
M COOLER ASSY-INTER		1.00	1779.00	00.00	1779.00
M SHIELD-AIR INTAKE		1.00	11.00	00.00	11.00
M DUCT ASSY-AIR		1.00	72.00	00.00	72.00
M CLEANER ASSY-AIR		1.00	119.00	00.00	119.00
M DUCT ASSY-EXTN		1.00	161.00	00.00	161.00
M HOSE ASSY-AIR INTAKE		1.00	295.00	00.00	295.00
M TENSIONER ASSY		1.00	284.00	00.00	284.00
M BODY ASSY-THROTTLE		1.00	636.00	00.00	636.00
M HOSE ASSY-OIL COOLER		1.00	22.00	00.00	22.00
M HOSE "A" ASSY-WATER		1.00	25.00	00.00	25.00
M VALVE ASSY-PURGE CONTROL		1.00	182.00	00.00	182.00
M MANIFOLD ASSY-INTAKE		1.00	500.00	00.00	500.00
M SENSOR-BOOST PRESSURE		1.00	141.00	00.00	141.00

Confirm &amp; accepted by

Nett 29,997.00  
 7% GST on 29997.00 2099.79  
**Total Payable 32,096.79**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.