

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21007550/EBS3Q2**Date:** 28/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0006751_01
Claimant Vehicle No :	SME180H	Insured Vehicle No :	SMG4506R
Date of Loss:	29/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002849

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME180H	Engine No:	F2253721B48B20B
Make & Model:	BMW 330I, 3.0 (A)	Chassis No:	WBA5R120X0FJ91953
Reg. Date:	13/08/2020 (Man. Year: 2020)	Odometer:	8101 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R19	Rear Tyre Size:	225/40 R19
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,409.95	1,369.00	1,040.95	43.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	2,015.00	2,175.00	51.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,599.95	3,384.00	3,215.95	48.73
+ GST 7.00/7.00% (S\$)	462.00	236.88	225.12	48.73

Nett Amount (S\$)	7,061.95	3,620.88	3,441.07	48.73
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,128.33		

INSPECTION

Date of Assignment: 12/07/2021

Date Inspected: 12/07/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2021)
Parts: 143	BMW 330I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SME180H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT LH SIDE PANEL	Not Necessary	815.60 FS	*- FS
3	1		*LH UPPER FRT DOOR HINGE	Not Necessary	16.30 FS	*- FS
4	1		*LH LOWER FRT DOOR HINGE	Not Necessary	56.30 FS	*- FS
5	1		*FRT LH DOOR	Dented	1,142.60 FS	*1,142.60 FS
6	1		*EMBLEM (M)	Not Necessary	82.75 FS	*- FS
7	1		*(S/L) DOOR WEATHERSTRIP	Necessary	146.40 FS	*146.40 FS
Total Parts (S\$)					2,409.95	1,369.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE LEFT FRONT SIDE PANEL ,LEFT FRONT DOOR	New	2,125.00	850.00
2	TO RESPRAY LEFT FRONT SIDE PANEL ,LEFT FRONT DOOR	New	1,770.00	885.00
3	TO CONDUCT CHECK ON ALL DOORS AND CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	168.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
			Gross Labour Cost (\$\$)	2,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >