

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007552/AGA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070030147
Claimant Vehicle No :	SGC8588U	Insured Vehicle No :	SMS5435S
Date of Loss:	11/07/2021	Nature of Claim:	TP
		Claim No:	8124342851SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC8588U	Engine No:	CVN022756
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF46HA063165
Reg. Date:	30/12/2016 (Man. Year: 2016)	Odometer:	102256 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,612.00	8,700.80	3,911.20	31.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,542.00	2,460.00	49.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,614.00	11,242.80	6,371.20	36.17
+ GST 7.00/7.00% (S\$)	1,232.98	787.00	445.98	36.17
Nett Amount (S\$)	18,846.98	12,029.80	6,817.18	36.17
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,231.80		

INSPECTION

Date of Assignment:	15/07/2021		
Date Inspected:	15/07/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	210.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	63.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	135.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Cracked	38.00 FS	*29.84 FS
8	1		*FRONT BUMPER TOP COVER -RH	Not Necessary	127.00 FS	*- FS
9	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
10	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
11	1		*FRONT FENDER -RH	Dented	767.00 FS	*613.20 FS
12	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
13	1		*FRONT FENDER CLOSING ELEMENT -RH	Damaged	72.00 FS	*57.52 FS
14	1		*FRONT FENDER BRACKET -RH	Not Necessary	35.00 FS	*- FS
15	1		*FRONT FENDER DEFORCMENTATION BRACKET -RH	Not Necessary	49.00 FS	*- FS
16	6		*FRONT FENDER RIVET	Not Necessary	20.00 FS	*- FS
17	1		*FRONT FENDER BRACE -RH	Bent	118.00 FS	*94.40 FS
18	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	241.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*FRONT WHEEL SPOILER RH	Not Necessary	73.00 FS	*- FS
21	1		*FRONT FENDER STONE CHIP GUARD -RH	Not Necessary	51.00 FS	*- FS
22	1		*FRONT FENDER TOP COVER -RH	Damaged	31.00 FS	*24.64 FS
23	1		*FRONT FENDER SIDE TOP COVER -RH	Damaged	23.00 FS	*17.92 FS
24	1		*FRONT HEADLIGHT -RH	Cracked	7,693.00 FS	*6,154.40 FS
25	1		*FRONT HEADLIGHT LIFT CYLINDER -RH	Not Necessary	210.00 FS	*- FS
26	1		*SUNDRIES	Necessary	250.00 FS	*20.08 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,612.00 8,700.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHTS RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >