



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107772

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 11/11/2021
Reference CC6/CTI21007555/Kes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLA 4654P
Insured Veh. SJN 2602H
Claim No. SNM21D203863/C02
Policy No. DMPCSNW00022782100
Accident Date 12/07/2021
Inspection Date 13/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21007555/Kes3q2	
			Date: 11/11/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 2602H		Veh. Inspected	SLA 4654P
Policy No.	DMPCSNW00022782100		Coverage (\$)	0.00
Claim No.	SNM21D203863/C02		Excess (\$)	0.00
Assign From			Assign Date	13/07/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	RU11102542		Colour	METALLIC MAROON
Odometer	194705 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		215/60 R16	YOKOHAMA	9 mm
L/H Front Tyre		215/60 R16	YOKOHAMA	9 mm
R/H Rear Tyre		215/60 R16	WINDSOR	3 mm
L/H Rear Tyre		215/60 R16	WINDSOR	3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	12/07/2021		Inspection Date	13/07/2021
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 4654P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	459.80	459.80
1	FRONT BUMPER TOW COVER	SERVICEABLE	17.10	-
1	FRONT BUMPER FOG LAMP	SERVICEABLE	327.70	-
1	FRONT BUMPER FOG LAMP COVER	DENTED	45.00	45.00
1	FRONT BUMPER LOWER SPOILER	SERVICEABLE	196.50	-
1	FRONT BUMPER RETAINER	DISTORTED	17.50	17.50
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
10	FRONT BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	FRONT GRILLE OUTER	CRACKED	203.40	203.40
1	FRONT GRILLE LOWER	SERVICEABLE	77.50	-
1	O/S HEAD LAMPS	CRACKED	1,952.70	1,859.40
1	O/S HEAD LAMPS BRACKET	CRACKED	35.00	35.00
1	O/S FRONT FENDER	BENT	421.10	421.10
1	O/S FRONT FENDER ARCH GARNISH	BENT	153.00	153.00
1	O/S FRONT FENDER UNDER SHIELD	DISTORTED	130.00	130.00
8	O/S FRONT FENDER UNDER SHIELD CLIPS @\$3.50	NECESSARY	28.00	28.00
1	WASHER TANK	DENTED	75.00	75.00
1	BONNET	BENT	892.30	892.30
1	BONNET INSULATOR	SERVICEABLE	122.30	-
	LESS 20% DISCOUNT		-1,101.98	-935.10
			4,407.92	3,740.40
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT.		1,000.00	700.00
	TO ANTI RUST.		150.00	60.00
	TO CHECK FRONT WIRING & FOCUS HEADLIGHT.		30.00	20.00
	LABOUR CHARGES.		650.00	540.00
			1,830.00	1,320.00
	GRAND TOTAL		6,237.92	5,060.40

Report Ref No. CC6/CTI21007555/Kes3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,050.00
---	--	--	----------

Report Ref No. CC6/CTI21007555/Kes3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 4654P

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 4654P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 4654P

RE-INSPECTION

