

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007558/APA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700017479
Claimant Vehicle No :	SMW196T	Insured Vehicle No :	SFK73K
Date of Loss:	30/06/2021	Nature of Claim:	TP
		Claim No:	0145088966SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW196T	Engine No:	DEM025387
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF41MN001126
Reg. Date:	29/10/2020 (Man. Year: 2020)	Odometer:	7964 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	350.00	500.00	58.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	850.00	350.00	500.00	58.82
+ GST 7.00/7.00% (S\$)	59.50	24.50	35.00	58.82
Nett Amount (S\$)	909.50	374.50	535.00	58.82
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		581.95		
Global Sum Settlement (S\$)		580.00		

INSPECTION

Date of Assignment:	09/07/2021		
Date Inspected:	09/07/2021	Inspected At:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21 Singapore 415875
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR	New	300.00	100.00
2	TO SPRAY PAINT REAR DOOR RIGHT	New	550.00	250.00
Gross Labour Cost (S\$)			850.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >