2/28/22, 12:26 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007561/TPA3Q2

28/02/2022 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100346727

**Claimant Vehicle** SHC1465A Insured Vehicle No: SKK5305A No:

Date of Loss: 10/07/2021 Nature of Claim: TP Claim No: 8319305211SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SHC1465A** 

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2F30858

Reg. Date: 05/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU103089171

Colour: Odometer: Blue 0 km

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,105.25	824.90	280.35	25.37
Miscellaneous Items		0.00	0.00	0.00	
Labour		840.00	690.00	150.00	17.86
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,945.25	1,514.90	430.35	22.12
	+ GST 7.00/7.00% (S\$)	136.17	106.04	30.13	22.13
	Nett Amount (S\$)	2,081.42	1,620.94	460.48	22.12
	+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	+ Car Rental (3.0 x S	\$126.47/day) (S\$)	379.41		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	2,152.35		
	Global Sui	m Settlement (S\$)	2,100.00		

**INSPECTION** 

Date of Assignment: 12/07/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 13/07/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID **CHEW HSIAO TONG** Adjuster: Manager:

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER REFLECTOR LAMP LH	Not Necessary	55.00 FL	*- FL
4	1		*REAR BUMPER LOWER COVER	Deformed	552.60 FL	*552.60 FL
5	1		*REAR BUMPER BEAM	Not Necessary	318.80 FL	*- FL
6	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,457.00	1,083.20
			- List Item Discount on L Ite	ems 25.00/25.00% (S\$)	351.75	258.30
				Total Parts (S\$)	1,105.25	824.90
			Report was unsubmitted during t	his print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

		***************************************
New	400.00	350.00
New	300.00	250.00
SENSOR New	80.00	30.00
New	60.00	60.00
Gross Labour Cost (S\$)	840.00	690.00
	SENSOR New New	New 300.00 E SENSOR New 80.00 New 60.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >