

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007562/BPA3Q2
Date: 14/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900009095
Claimant Vehicle No :	SLJ7029C	Insured Vehicle No :	SMH5748Y
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	6004980961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ7029C		
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Engine No:	L15B31190541
Reg. Date:	21/12/2016 (Man. Year: 2016)	Chassis No:	JHMGK5850HX200794
Colour:	Grey	Odometer:	70164 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,339.52	7,443.44	10,896.08	59.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,670.00	2,740.00	3,930.00	58.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,009.52	10,183.44	14,826.08	59.28
Approved Total (Overridden) (S\$)		8,150.00		

(S\$)	25,009.52	8,150.00	16,859.52	67.41
+ GST 7.00/7.00% (S\$)	1,750.67	570.50	1,180.17	67.41
Nett Amount (S\$)	26,760.19	8,720.50	18,039.69	67.41
+ Loss of Use (16.0 x S\$50.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		21.40		
Nett Liability (S\$)		9,549.35		
Global Sum Settlement (S\$)		9,540.00		

INSPECTION

Date of Assignment: 12/07/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,085.20 FL	*730.60 FL
2	1		*TAILGATE LOGO	Necessary	86.20 FL	*24.00 FL
3	1		*TAILGATE EMBLEM JAZZ	Necessary	83.40 FL	*32.20 FL
4	1		*TAILGATE INNER LOCK	Jammed	389.20 FL	*211.90 FL
5	1		*TAILGATE INNER LOCK STRIKER	Not Damaged	48.90 FL	*- FL
6	1		*TAILGATE OUTER CHROME GARNISH	Broken	469.20 FL	*234.40 FL
7	2		*TAILGATE LAMP	Not Damaged	1,166.40 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Torn	286.30 FL	*138.00 FL
9	1		*TAILGATE INNER TRIM BOARD	Broken	486.20 FL	*285.90 FL
10	1		*TAILGATE INNER HANDLE	Not Damaged	105.20 FL	*- FL
11	1		*TAILGATE BUZZER	Broken	286.40 FL	*150.00 FL
12	1		*TAILGATE ANTENNA SENSOR	Broken	389.40 FL	*180.50 FL
13	2		*TAILGATE NO PLATE LAMP	Not Damaged	204.60 FL	*- FL
14	1		*TAILGATE SOLLENOLD SWITCH	No such part	367.50 FL	*- FL
15	1		*TAILGATE WINDSCREEN MOULDING	Necessary	205.30 FL	*205.30 FL
16	1		*TAILGATE WINDSCREEN WIPER MOTOR	Not Damaged	423.50 FL	*- FL
17	1		*REAR BUMPER	Broken	1,064.30 FL	*721.10 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	287.20 FL	*52.00 FL
19	2		*REAR BUMPER BRACKET	No such part	207.00 FL	*- FL
20	2		*REAR BUMPER GARNISH (SIDE)	Broken	572.80 FL	*310.00 FL
21	1		*REAR END PANEL	Dented	1,045.80 FL	*460.00 FL
22	1		*REAR END PANEL TOP GARNISH	Broken	256.30 FL	*180.00 FL
23	1		*SPARE TYRE PANEL	Dented	986.40 FL	*897.30 FL
24	1		*SPARE TYRE PANEL TOP BOARD	No such part	250.00 FL	*- FL
25	1		*SPARE TYRE PANEL INSULATOR	Necessary	269.10 FL	*150.00 FL
26	1		*SPARE TYRE PANEL SPONGE BOX	Broken	486.30 FL	*230.00 FL
27	1		*TAILLAMP RH	Broken	853.40 FL	*833.50 FL
28	1		*TAILLAMP LOWER BRACKET RH	No such part	145.60 FL	*- FL
29	1		*TAILLAMP BASE PANEL RH	Dented	465.80 FL	*158.00 FL
30	1		*TAILLAMP LH	Broken	853.40 FL	*833.50 FL
31	1		*TAILLAMP LOWER BRACKET LH	No such part	145.60 FL	*- FL
32	1		*TAILLAMP BASE PANEL LH	Dented	465.80 FL	*158.00 FL
33	1		*REAR FENDER RH	Dented	986.20 FL	*559.20 FL
34	1		*REAR FENDER INNER TRIM RH	Torn	473.50 FL	*258.40 FL
35	1		*REAR FENDER INNER COWLING	Not Damaged	146.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER QUARTER GLASS MOULDING (RH)	Necessary	103.50 FL	*89.60 FL
37	1		*REAR FENDER AIR VENTS	Not Damaged	84.00 FL	*- FL
38	1		*REAR FENDER LH	Not Damaged	986.20 FL	*- FL
39	1		*REAR FENDER INNER TRIM LH	Broken	473.50 FL	*258.40 FL
40	1		*REAR DOOR RH	Repair	957.60 FL	*- FL
41	1		*REAR DOOR LOCK RH	Not Damaged	463.50 FL	*- FL
42	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
43	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
44	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
45	1		*TAILGATE LAMP SEAL	Not Necessary	60.00 FS	*- FS
46	1		*TAILGATE LAMP CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*TAILGATE INNER TRM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
48	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
49	1		*TAILGATE WINDSCREEN CLIPS	Necessary	50.00 FS	*20.00 FS
50	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
51	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
52	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
53	1		*REAR BUMPER REFLECTOR GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
55	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
56	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
57	2		*TAILLAMP SEAL	Necessary	120.00 FS	*40.00 FS
58	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
59	1		*REAR FENDER SEALANT	O/S Necessary	200.00 FS	*30.00 FS
60	2		*REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FS	*40.00 FS
61	1		*REAR FENDER INNER COWLING CLIPS RH	Not Necessary	50.00 FS	*- FS
62	1		*REAR FENDER QUARTER GLASS SEALANT	O/S Necessary	200.00 FS	*30.00 FS
63	2		*REAR FENDER QUARTER GLASS CLIPS	Not Necessary	100.00 FS	*- FS
64	1		*REAR FENDER QUARTER GLASS INNER SEAL	O/S Necessary	120.00 FS	*20.00 FS
65	2		*REAR FENDER QUARTER GLASS PRIMER & CLEANER	Not fitted	160.00 FS	*- FS
66	1		*OPC SEAL	Necessary	60.00 FS	*60.00 FS
67	1		*REVERSE SENSOR	Scratched	250.00 FS	*200.00 FS
68	1		*REVERSE CAMERA	Not Damaged	480.00 FS	*- FS
69	1		*REAR NUMBER PLATE W/CASING	Dented	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,161.90	9,111.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,822.38	1,668.36
Total Parts (\$\$)	18,339.52	7,443.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	100.00	70.00
2	R&R REAR WINDSCREEN	New	250.00	120.00
3	R&R REAR FENDER QUARTER GLASS LH AND RH	New	500.00	60.00
4	R&R REVERSE SENSOR	New	100.00	60.00
5	R&R REVERSE CAMERA	New	100.00	0.00
6	R&R REAR DOOR COMPONENT	New	100.00	0.00
7	MOUNT BENCH WORK	New	350.00	0.00
8	REAR CHASIS ALIGNMENT	New	300.00	0.00
9	R&R UPHOLSTERY	New	300.00	0.00
10	CHECK WIRING	New	120.00	30.00
11	DIAGNOSTIC & RESET FAULT CODE	New	300.00	0.00
12	PANEL BEATING	New	2,000.00	1,200.00
13	RUST PROOFING	New	150.00	0.00
14	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			6,670.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >