

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21007568/EVF3N2**Date:** 23/08/2021**REFERENCE**

|                   |             |                  |            |                        |
|-------------------|-------------|------------------|------------|------------------------|
| Insured/Claimant: | ONG JIAN DE | Policy No:       | 1900009095 |                        |
| Date of Loss:     | 10/07/2021  | Nature of Claim: | OD         | Claim No: 6004980961SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMH5748Y</b>                   |             |                   |
| Make & Model:               | KIA CERATO, 1.6 (A)               | Engine No:  | G4FGJH713608      |
| Reg. Date:                  | 28/01/2019 (Man. Year: 2018)      | Chassis No: | KNAF3416MK5024748 |
| Colour:                     | Grey                              | Odometer:   | 23457 km          |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | S\$70,000.00                      |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 205/55R16  | Rear Tyre Size:  | 205/55R16  |
| Front Left Side:  | NFERA 4 mm | Rear Left Side:  | NFERA 4 mm |
| Front Right Side: | NFERA 4 mm | Rear Right Side: | NFERA 4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 13,079.60         | 9,620.00          | 3,459.60          | 26.45         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 14,350.00         | 8,430.00          | 5,920.00          | 41.25         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>27,429.60</b>  | <b>18,050.00</b>  | <b>9,379.60</b>   | <b>34.20</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>1,920.07</b>   | <b>1,263.50</b>   | <b>656.57</b>     | <b>34.20</b>  |
| <b>Nett Amount (S\$)</b>      | <b>29,349.67</b>  | <b>19,313.50</b>  | <b>10,036.17</b>  | <b>34.20</b>  |

**INSPECTION**

|                             |            |                                                                                                       |
|-----------------------------|------------|-------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 13/07/2021 |                                                                                                       |
| Date Inspected:             | 13/07/2021 | Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)<br>209 Pandan Gardens<br>Singapore 609339 |
| Estimated Period of Repair: | 18.0 days  |                                                                                                       |

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *COVER-FR BUMPER                | Crushed       | 633.00 FL   | *633.00 FL   |
| 2   | 1   |          | *GRILLE-FRONT BUMPER            | Cut           | 262.00 FL   | *262.00 FL   |
| 3   | 1   |          | *GRILLE ASSY-RADIATOR           | Cracked       | 328.00 FL   | *328.00 FL   |
| 4   | 1   |          | *ABSORBER-FRONT BUMPER ENERGY   | Broken        | 84.00 FL    | *84.00 FL    |
| 5   | 1   |          | *STIFFNER-FR BPR LWR            | Not Necessary | 114.00 FL   | *- FL        |
| 6   | 1   |          | *BRACKET-FR BUMPER UPR SIDE MTG | Not Necessary | 22.00 FL    | *- FL        |
| 7   | 1   |          | *BRACKET-FR BUMPER UPR SIDE MTG | Not Necessary | 22.00 FL    | *- FL        |
| 8   | 1   |          | *PANEL ASSY-HOOD                | Dented        | 1,502.00 FL | *1,502.00 FL |
| 9   | 1   |          | *BEAM COMPLETE-FR BUMPER        | Not Necessary | 497.00 FL   | *- FL        |
| 10  | 1   |          | *CARRIER ASSY-FRONT END MODULE  | Not Necessary | 675.00 FL   | *- FL        |
| 11  | 1   |          | *ORNAMENT-KIA NO,115            | Necessary     | 32.00 FL    | *32.00 FL    |
| 12  | 1   |          | *LOGO ASSY-KIA SUB              | Necessary     | 32.00 FL    | *32.00 FL    |
| 13  | 1   |          | *EMBLEM-CERATO                  | Necessary     | 28.00 FL    | *28.00 FL    |
| 14  | 1   |          | *COVER-RR BUMPER                | Broken        | 651.00 FL   | *651.00 FL   |
| 15  | 1   |          | *COVER-RR BUMPER LWR            | Broken        | 241.00 FL   | *241.00 FL   |
| 16  | 1   |          | *COVER-RR BUMPER UNDER,LH       | Not Necessary | 33.00 FL    | *- FL        |
| 17  | 1   |          | *COVER-RR BUMPER FOG LAMP,LH    | Cut           | 19.00 FL    | *19.00 FL    |
| 18  | 1   |          | *COVER-RR BUMPER FOG LAMP,RH    | Cut           | 19.00 FL    | *19.00 FL    |
| 19  | 1   |          | *LAMP ASSY-SIDE T/SIGNAL,LH     | Broken        | 181.00 FL   | *181.00 FL   |
| 20  | 1   |          | *LAMP ASSY-SIDE T/SIGNAL,RH     | Not Necessary | 181.00 FL   | *- FL        |
| 21  | 1   |          | *EXTN WIRING ASSY-BWS           | Not Necessary | 207.00 FL   | *- FL        |
| 22  | 1   |          | *BEAM-RR BUMPER                 | Broken        | 318.00 FL   | *318.00 FL   |
| 23  | 1   |          | *BRACKET-RR BEAM UPR MTG,RH     | Not Necessary | 9.00 FL     | *- FL        |
| 24  | 1   |          | *BRACKET-RR BEAM UPR MTG,LH     | Broken        | 9.00 FL     | *9.00 FL     |
| 25  | 1   |          | *BRACKET-RR BEAM LWR,CTR        | Broken        | 6.00 FL     | *6.00 FL     |
| 26  | 1   |          | *BRACKET-RR BEAM LWR MTG        | Not Necessary | 6.00 FL     | *- FL        |
| 27  | 1   |          | *ANTENNA ASSY-SMARTKEY          | Not Necessary | 46.00 FL    | *- FL        |
| 28  | 1   |          | *STAY-RR BUMPER LH              | Bent          | 65.00 FL    | *65.00 FL    |
| 29  | 1   |          | *STAY-RR BUMPER RH              | Bent          | 65.00 FL    | *65.00 FL    |
| 30  | 1   |          | *COVER-RR BUMPER UNDER,RH       | Not Necessary | 33.00 FL    | *- FL        |
| 31  | 1   |          | *BRACKET ASSY-RR BPR SIDE UPR,L | Not Necessary | 25.00 FL    | *- FL        |
| 32  | 1   |          | *BRACKET ASSY-RR BPR SIDE UPR,R | Not Necessary | 31.00 FL    | *- FL        |
| 33  | 1   |          | *PANEL ASSY-TRUNK LID           | Dented        | 1,297.00 FL | *1,297.00 FL |
| 34  | 1   |          | *HINGE ASSY-TRUNK LID,LH        | Not Necessary | 97.00 FL    | *- FL        |
| 35  | 1   |          | *HINGE ASSY-TRUNK LID,RH        | Not Necessary | 97.00 FL    | *- FL        |
| 36  | 1   |          | *PANEL ASSY-BACK                | Dented        | 324.00 FL   | *324.00 FL   |
| 37  | 1   |          | *TRIM ASSY-RR TRANSVERSE        | Crushed       | 41.00 FL    | *41.00 FL    |
| 38  | 1   |          | *MAT ASSY-LUGGAGE COVERING      | Not Necessary | 211.00 FL   | *- FL        |
| 39  | 1   |          | *W/STRIP-TRUNK LID OPNG         | Crushed       | 100.00 FL   | *100.00 FL   |
| 40  | 1   |          | *LATCH ASSY-TRUNK LID           | Bent          | 112.00 FL   | *112.00 FL   |
| 41  | 1   |          | *STRIKER ASSY-TRUNK LID         | Bent          | 40.00 FL    | *40.00 FL    |
| 42  | 1   |          | *LAMP ASSY-REAR COMB INSIDE,LH  | Not Necessary | 608.00 FL   | *- FL        |
| 43  | 1   |          | *LAMP ASSY-REAR COMB INSIDE,RH  | Not Necessary | 608.00 FL   | *- FL        |
| 44  | 1   |          | *LAMP ASSY-REAR COMB OUTSIDE,LH | Broken        | 675.00 FL   | *675.00 FL   |
| 45  | 1   |          | *LAMP ASSY-REAR COMB OUTSIDE,RH | Cut           | 675.00 FL   | *675.00 FL   |
| 46  | 1   |          | *LAMP ASSY-CENTER GARNISH       | Not Necessary | 690.00 FL   | *- FL        |
| 47  | 1   |          | *FILM-ANTI CHIPPG RH            | Necessary     | 27.00 FL    | *27.00 FL    |
| 48  | 1   |          | *FILM-ANTI CHIPPG LH            | Necessary     | 27.00 FL    | *27.00 FL    |
| 49  | 1   |          | *SUNDRIES                       | Necessary     | 30.00 FS    | *30.00 FS    |
| 50  | 1   |          | *BODY PNL SEALANT               | Necessary     | 80.00 FS    | *40.00 FS    |
| 51  | 1   |          | *REVERSE SENSOR                 | Broken        | 220.00 FS   | *220.00 FS   |
| 52  | 1   |          | *FR NUMBER PLATE WITH CASING    | Broken        | 50.00 FS    | *50.00 FS    |
| 53  | 1   |          | *RR NUMBER PLATE WITH CASING    | Not Necessary | 50.00 FS    | *- FS        |
| 54  | 1   |          | *C&C BADGE                      | Necessary     | 40.00 FS    | *40.00 FS    |
| 55  | 1   |          | *GARNISH-RADIATOR GRILLE        | Broken        | 38.00 FL    | *38.00 FL    |

(Supplementary)

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                               | Condition | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------------------------|-----------|-------------|--------------|
| 56  | 1   |          | <b>*COVER-FR BUMPER FOG LAMP,LH</b><br>(Supplementary)    | Cut       | 15.00 FL    | *15.00 FL    |
| 57  | 1   |          | <b>*TRIM ASSY-TRUNK LID</b><br>(Supplementary)            | Crushed   | 202.00 FL   | *202.00 FL   |
| 58  | 1   |          | <b>*PROTECTOR-HEAT REAR</b><br>(Supplementary)            | Bent      | 136.00 FL   | *136.00 FL   |
| 59  | 1   |          | <b>*PANEL ASSY-REAR FLOOR,RR</b><br>(Supplementary)       | Dented    | 219.00 FL   | *219.00 FL   |
| 60  | 1   |          | <b>*REINF-RR SPARE TIRE WELL CROSS</b><br>(Supplementary) | Necessary | 41.00 FL    | *41.00 FL    |
| 61  | 1   |          | <b>*HOOK-TOWING</b><br>(Supplementary)                    | Necessary | 16.00 FL    | *16.00 FL    |
| 62  | 1   |          | <b>*REINF-TOWING HOOK</b><br>(Supplementary)              | Necessary | 14.00 FL    | *14.00 FL    |
| 63  | 1   |          | <b>*PANEL ASSY-QUARTER OUTER,RH</b><br>(Supplementary)    | Dented    | 1,349.00 FL | *1,349.00 FL |
| 64  | 1   |          | <b>*PANEL ASSY-QUARTER OUTER,LH</b><br>(Supplementary)    | Dented    | 1,349.00 FL | *1,349.00 FL |
| 65  | 1   |          | <b>*PANEL ASSY-RR COMB LAMP HSG,RH</b><br>(Supplementary) | Dented    | 135.00 FL   | *135.00 FL   |
| 66  | 1   |          | <b>*PANEL ASSY-RR COMB LAMP HSG,LH</b><br>(Supplementary) | Dented    | 139.00 FL   | *139.00 FL   |
| 67  | 1   |          | <b>*PAD-WINDSHIELD GLASS</b><br>(Supplementary)           | Necessary | 2.00 FL     | *2.00 FL     |
| 68  | 10  |          | <b>*FASTENER</b><br>(Supplementary)                       | Necessary | 10.00 FL    | *10.00 FL    |
| 69  | 10  |          | <b>*CLIP</b><br>(Supplementary)                           | Necessary | 20.00 FL    | *20.00 FL    |
| 70  | 2   |          | <b>*SILENCER,FLOOR</b><br>(Supplementary)                 | Necessary | 26.00 FL    | *26.00 FL    |
| 71  | 1   |          | <b>*ANTENNA ASSY-SMARTKEY</b><br>(Supplementary)          | Broken    | 46.00 FL    | *46.00 FL    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                  |
|-----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (S\$)</b>                                    | <b>16,232.00</b> | <b>11,930.00</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> | 3,152.40         | 2,310.00         |
| <b>Total Parts (S\$)</b>                                  | <b>13,079.60</b> | <b>9,620.00</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars           | Repairer's  | Amount      |
|----------------------------|-----|-----------------------|-------------|-------------|
| <b>Miscellaneous Items</b> |     |                       |             |             |
| 1                          | 1   | *OD/TP Case (Insurer) | -           | 0.00        |
| <b>Sub Total (\$\$)</b>    |     |                       | <b>0.00</b> | <b>0.00</b> |

## Recommended Labour

| No                              | Particulars                                                                                                                                        | Lab.Type | Repairer's       | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                    |          |                  |                 |
| 1                               | RENEW (FR PORTION) FR BUMPER,BONNET & FR SUPPORT<br>REPAIR LHF FENDER & RHF FENDER                                                                 | New      | 2,000.00         | 600.00          |
| 2                               | RENEW RR BUMPER,RR END PNL & BOOTLID.REPAIR RR FLR<br>PNL,LHR FENDER,RHR FENDER,RR CHASSIS & LHR DOOR                                              | New      | 4,000.00         | 1,800.00        |
| 3                               | RESPRAY FRT BUMPER,BONNET,LHF FENDER,RHF FENDERRR<br>BUMPER,RR END PNL,RR FLR PNL,LHR FENDER,RHR FENDER,RR<br>CHASSIS,LHF DOOR,RHF DOOR & LHR DOOR | New      | 4,200.00         | 2,100.00        |
| 4                               | REMOVE & REFIT AC COND & RADIATOR                                                                                                                  | New      | 100.00           | 0.00            |
| 5                               | TOP UP AC GAS                                                                                                                                      | New      | 80.00            | 0.00            |
| 6                               | REMOVE & REFIT BOOTLID COMPONENT                                                                                                                   | New      | 120.00           | 120.00          |
| 7                               | REMOVE & REFIT RR FLR BOARD,TRIM,CARPET & SEAT                                                                                                     | New      | 120.00           | 120.00          |
| 8                               | CHECK WIRING ELECTRICAL SYSTEM                                                                                                                     | New      | 30.00            | 30.00           |
| 9                               | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL<br>SYSTEM                                                                                      | New      | 120.00           | 120.00          |
| 10                              | TO RENEW REVERSE SENSOR                                                                                                                            | New      | 80.00            | 80.00           |
| 11                              | APPLY ANTI CORROSION ON AFFECTED AREAS                                                                                                             | New      | 80.00            | 40.00           |
| 12                              | REMOVE & INSTALL FUEL TANK ASSY<br>(Supplementary)                                                                                                 | New      | 200.00           | 200.00          |
| 13                              | REPLACE FLOOR PANEL,BOTH REAR QTR PANEL,REPAIR BOTH<br>CHASSIS<br>(Supplementary)                                                                  | New      | 2,200.00         | 2,200.00        |
| 14                              | REMOVE & REFIT REAR WINDSCREEN GLASS<br>(Supplementary)                                                                                            | New      | 240.00           | 240.00          |
| 15                              | SUPPLY REAR WINDSCREEN GLASS SEALANT<br>(Supplementary)                                                                                            | New      | 80.00            | 80.00           |
| 16                              | SPRAY PAINT BOOT LID & RH REAR QUARTER PANEL<br>(Supplementary)                                                                                    | New      | 700.00           | 700.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                    |          | <b>14,350.00</b> | <b>8,430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >