

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007572/EVF3N2**Date:** 16/09/2021**REFERENCE**

Insured/Claimant:	CHEN KAIWEN,KELVIN	Policy No:	1900111039	
Date of Loss:	10/07/2021	Nature of Claim:	OD	Claim No: 4345925913SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3638Y	Engine No:	G4FGKH742900
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5048435
Reg. Date:	02/07/2019 (Man. Year: 2019)	Odometer:	44628 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	NFERA 4 mm	Rear Left Side:	NFERA 4 mm
Front Right Side:	NFERA 4 mm	Rear Right Side:	NFERA 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,490.69	18,533.49	1,957.20	9.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,850.00	6,640.00	7,210.00	52.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,340.69	25,173.49	9,167.20	26.69
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	34,040.69	24,873.49	9,167.20	26.93
+ GST 7.00/7.00% (S\$)	2,382.85	1,741.14	641.71	26.93
Nett Amount (S\$)	36,423.54	26,614.63	9,808.91	26.93

INSPECTION

Date of Assignment:	13/07/2021	
Date Inspected:	13/07/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Missing	633.00 FL	*633.00 FL
2	1		*CAP-FRONT HOOK	Missing	9.00 FL	*9.00 FL
3	1		*GRILLE-FRONT BUMPER	Missing	485.00 FL	*485.00 FL
4	1		*COVER-FR BUMPER FOG LAMP,LH	Missing	15.00 FL	*15.00 FL
5	1		*COVER-FR BUMPER FOG LAMP,RH	Missing	15.00 FL	*15.00 FL
6	1		*LAMP ASSY-FRONT FOG,LH	Missing	303.00 FL	*303.00 FL
7	1		*LAMP ASSY-FRONT FOG,RH	Missing	303.00 FL	*303.00 FL
8	1		*MOULDING-FRONT BUMPER,LH	Missing	216.00 FL	*216.00 FL
9	1		*MOULDING-FRONT BUMPER,RH	Missing	216.00 FL	*216.00 FL
10	1		*LAMP ASSY-SIDE REPEATER,LH	Missing	143.00 FL	*143.00 FL
11	1		*LAMP ASSY-SIDE REPEATER,RH	Missing	143.00 FL	*143.00 FL
12	1		*AIR DUCT-FR BUMPER,LH	Broken	14.00 FL	*14.00 FL
13	1		*AIR DUCT-FR BUMPER,RH	Missing	14.00 FL	*14.00 FL
14	1		*ABSORBER-FRONT BUMPER ENERGY	Missing	84.00 FL	*84.00 FL
15	1		*STIFFNER-FR BPR LWR	Crushed	114.00 FL	*114.00 FL
16	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
17	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
18	4		*ULTRASONIC SENSOR ASSY-P.A.S	Missing	652.00 FL	*652.00 FL
19	1		*WIRING ASSY-BUMPER EXTENSION	Torn	207.00 FL	*207.00 FL
20	1		*GARNISH-RADIATOR GRILLE	Missing	38.00 FL	*38.00 FL
21	1		*ORNAMENT-KIA NO 115	Missing	32.00 FL	*32.00 FL
22	1		*LAMP ASSY-HEAD,LH	Broken	2,210.00 FL	*2,210.00 FL
23	1		*LAMP ASSY-HEAD,RH	Cut	2,210.00 FL	*2,210.00 FL
24	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
25	1		*HINGE ASSY-HOOD,LH	Bent	43.00 FL	*43.00 FL
26	1		*HINGE ASSY-HOOD,RH	Bent	43.00 FL	*43.00 FL
27	1		*PANEL-FENDER,LH	Dented	430.00 FL	*430.00 FL
28	1		*PANEL-FENDER,RH	Dented	430.00 FL	*430.00 FL
29	1		*INSULATOR-FENDER LH	Not Necessary	27.00 FL	*- FL
30	1		*INSULATOR-FENDER RH	Not Necessary	27.00 FL	*- FL
31	1		*PAD-HOOD INSULATING	Not Necessary	156.00 FL	*- FL
32	1		*LATCH ASSY-HOOD	Bent	103.00 FL	*103.00 FL
33	1		*GUARD ASSY-FRONT WHEEL,LH	Not Necessary	95.00 FL	*- FL
34	1		*GUARD ASSY-FRONT WHEEL,RH	Not Necessary	95.00 FL	*- FL
35	1		*PANEL ASSY-UNDER COVER	Broken	117.00 FL	*117.00 FL
36	1		*GLASS-WINDSHIELD	Not Necessary	821.00 FL	*- FL
37	1		*MOULDING-WINDSHIELD GLASS	Not Necessary	56.00 FL	*- FL
38	1		*COVER ASSY-COWL TOP	Broken	247.00 FL	*247.00 FL
39	1		*CLEANER ASSY-AIR	Broken	174.00 FL	*174.00 FL
40	1		*DUCT-EXTENSION	Crushed	5.00 FL	*5.00 FL
41	1		*SHIELD-AIR INTAKE	Crushed	9.00 FL	*9.00 FL
42	1		*DUCT-ASSY AIR	Crushed	55.00 FL	*55.00 FL
43	1		*DUCT ASSY-EXTENSION	Broken	115.00 FL	*115.00 FL
44	1		*RESERVOIR & PUMP ASSY-WASHER	Not Necessary	146.00 FL	*- FL
45	1		*GUARD-AIR,LH	Missing	28.00 FL	*28.00 FL
46	1		*GUARD-AIR,RH	Broken	28.00 FL	*28.00 FL
47	1		*CONDENSER ASSY-COOLER	Bent	687.00 FL	*687.00 FL
48	1		*RADIATOR ASSY	Bent	646.00 FL	*646.00 FL
49	1		*BLOWER ASSY	Broken	656.00 FL	*656.00 FL
50	1		*HOSE ASSY-RADIATOR,LWR	Not Necessary	40.00 FL	*- FL
51	1		*FILLER NECK ASSY-RADIATOR	Not Necessary	28.00 FL	*- FL
52	1		*HOSE ASSY-RADIATOR,UPR	Crushed	27.00 FL	*27.00 FL
53	1		*HOSE RADIATOR INLET	Not Necessary	31.00 FL	*- FL
54	1		*BRACKET ASSY-ENGINE SUPT	Not Necessary	107.00 FL	*- FL
55	1		*BRACKET ASSY-ENG MTG	Not Necessary	93.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BRACKET ASSY-ENGINE MTG	Not Necessary	208.00 FL	*- FL
57	1		*BRACKET ASSY-TRANSMISSION MTG	Not Necessary	204.00 FL	*- FL
58	1		*BRACKET ASSY-ROLL ROD	Not Necessary	150.00 FL	*- FL
59	1		*CROSSMEMBER COMPL	Bent	1,156.00 FL	*1,156.00 FL
60	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
61	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
62	1		*WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*SENSOR ASSY-KNOCK (Supplementary)	Broken	108.00 FL	*108.00 FL
64	1		*STARTER ASSY (Supplementary)	Broken	686.00 FL	*686.00 FL
65	1		*TUBE ASSY-SUCTION & LIQUID (Supplementary)	Bent	462.00 FL	*462.00 FL
66	1		*HOSE-DISCHARGE (Supplementary)	Bent	122.00 FL	*122.00 FL
67	1		*TRAY ASSY-BATTERY (Supplementary)	Broken	49.00 FL	*49.00 FL
68	1		*UPR COVER-ENG ROOM BOX (Supplementary)	Cut	26.00 FL	*26.00 FL
69	1		*LOWER COVER-U/H J/BOX (Supplementary)	Broken	13.00 FL	*13.00 FL
70	1		*COVER-VALVE BODY (Supplementary)	Broken	142.00 FL	*142.00 FL
71	1		*TUBE ASSY-FEED (Supplementary)	Bent	56.00 FL	*56.00 FL
72	1		*WIRING ASSY-CONTROL (Supplementary)	Broken	966.00 FL	*966.00 FL
73	1		*SWITCH ASSY-OIL PRESSURE (Supplementary)	Bent	26.00 FL	*26.00 FL
74	1		*BEAM COMPLETE-FR BUMPER (Supplementary)	Bent	497.00 FL	*497.00 FL
75	1		*CARRIER ASSY-FRONT END MODULE (Supplementary)	Broken	675.00 FL	*675.00 FL
76	1		*GRILLE ASSY-RADIATOR (Supplementary)	Missing	328.00 FL	*328.00 FL
77	1		*T/SCREW-FLANGE HEAD (30 Pcs)(Supplementary)	Necessary	30.00 FL	*30.00 FL
78	1		*WIRING ASSY-FEM (Supplementary)	Missing	143.00 FL	*143.00 FL
79	1		*CLIP (30 Pcs)(Supplementary)	Necessary	30.00 FL	*30.00 FL
80	1		*RETAINER-COWL TOP COVER MTG (10 Pcs)(Supplementary)	Necessary	20.00 FL	*20.00 FL
81	2		*CLIP-HEAD LAMP MTG (Supplementary)	Missing	8.00 FL	*8.00 FL
82	2		*BUMPER-HOOD OVERSIAM (Supplementary)	Missing	2.00 FL	*2.00 FL
83	1		*BUMPER-DR OVERSIAM (Supplementary)	Necessary	4.00 FL	*4.00 FL
84	1		*BLOCK ASSY-CYLINDER (Supplementary)	Broken	3,747.00 FL	*3,747.00 FL
85	1		*GASKET-WATER PUMP (Supplementary)	Necessary	7.00 FL	*7.00 FL
86	1		*BRACKET ASSY-FENDER & BUMPER,L (Supplementary)	Broken	9.00 FL	*9.00 FL
87	1		*FILTER ASSY-ENGINE OIL (Supplementary)	Necessary	14.00 FL	*14.00 FL
88	1		*GASKET-OIL PLUG (Supplementary)	Necessary	2.00 FL	*2.00 FL
89	1		*AUTO TRANSMISSION OIL (4 Pcs)(Supplementary)	Necessary	112.00 FL	*112.00 FL
90	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
91	1		*BUZZER ASSY-PIEZO (Supplementary)	Missing	68.00 FL	*68.00 FL
92	1		*ULTRA S-HELIX (3.6L) (Supplementary)	Necessary	90.29 FS	*90.29 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,543.29	23,129.29
- List Item Discount on L Items 20.00/20.00% (\$)	5,052.60	4,595.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	20,490.69
						18,533.49
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER,FR SUPPORT,BONNET,LHF FENDER & RHF FENDER.REPAIR LHF DOOR,RHF DOOR,LHF WHEELHOUSE,RHF WHEELHOUSE,LHF A PILLAR,RHF A PILLAR & BOTH FR CHASSIS	New	4,000.00	1,600.00
2	RESPRAY FR BUMPER,BONNET,LHF FENDER,LHF WHEELHOUSE,LHF A PILLAR,LHF DOOR,RHF FENDER,RHF WHEELHOUSE,RHF A PILLAR,RHF DOOR & BOTH FR CHASSIS	New	4,200.00	1,750.00
3	RENEW AIRCON CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	REMOVE & REFIT ENGINE ASSY & GEARBOX TO GIVE WAY FOR REPAIR	New	800.00	400.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH	New	1,000.00	0.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	TO RENEW FR WINDSCREEN GLASS	New	240.00	0.00
11	INSTALL FR WINDSCREEN SOLAR FILM	New	280.00	0.00
12	SUPPLY FR NUMBER PLATE WITH CASING	New	50.00	50.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
14	TO RENEW FR X-MEMBER,ENGINE & GEARBOX MOUNTING	New	800.00	400.00
15	REPAIR LH & RH CHASSIS FRONT (Supplementary)	New	800.00	800.00
16	SPRAY PAINT LH & RH CHASSIS FRONT (Supplementary)	New	350.00	350.00
17	RENEW ENGINE BLOCK LOWER & REPAIR OIL SUMP (Supplementary)	New	800.00	800.00
Gross Labour Cost (\$\$)			13,850.00	6,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >