

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



CCT Day No . MP-8500111-X

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Down	0-1
Co Reg No : 199405410K	FOTIMATE
100 ATOK	ESTIMATE

	COTIVIATE	GST REG NO : MR-0300222
Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/CHEN KAIWEN, KELVIN
cu.	Reg No/Reg Date	SLE3638Y / 02/07/201
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 44628
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	KNAF3416MK5048435
SINGAPORE 079120		G4FGKH742900
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	THE PARTY OF		
LAX00000	Credit	12/07/2021/ 18:10	BLE	261 / Edwin Caina		35992			
-	PER BURN	Description of Good	s / Service	es	Qty	Unit Price	Disc%	Am	ount
REPAIR LI	HF DOOR ,	2	T , LHF ELHOUSE	FENDER & RHF FENDER 4, RHF WHEELHOUSE,	x 4	100			4000.00
t RHF DOOR	LLAR 🎜 LI	HF DOOR , RHF FENDER	DER , LH , RHF W	F WHEELHOUSE , 5 X HEELHOUSE , RHF A PILLAR	350			1750	100.00
E PNT88000 RENEW AI	RCON CON	DENSER & RADIATOR							80.00
M SUNDRY TOP UP A	TRCON GAS		$\mathcal{I}_{\mathcal{I}}$		3	2			
			25 W	SWAY FOR REPAIR C	CAR	To To		490	800.00
					CPIC				30.00
A 10028901		CTRICAL SYSTEM & ADJ							120.0
TO CARRY E PNT88000	OUT DIAG	NOSTIC CHECK ON ELE	CTRONIC	CONTROL SYSTEM				*	1000.0
CONDUCT (LIGNMENT-CELETTE BE	NCH					'	120.0
A WHEELALIGN To Conduc		erize Full Wheel Al	ignment					.,	
PNT88000	FR WINDS	CREEN GLASS						X	240.0
SUNDRY								X	280.0
INSTALL F I SUNDRY	K MIND2C	REEN SOLAR FILM						À	80.0
SUPPLY WI SUNDRY	NDSCREEN	SEALANT							50.0
SUPPLY FR	NUMBER	PLATE WITH CASING						100	
SUNDRY APPLY ANT	T CORROS	ION ON AFFECTED ARE	AS					40	80.0
SUNDRY	COMMOS							49	80.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing cheque. You must also agree to pay full amount for renewal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

			GST REG NO . FIR COURT			
1000	Invoice Name & Address	Owner Name & Vehicle Info				
	AIG Asia Pacific Insurance Pte.	Cust No/Name	/CHEN KAIWEN, KELVIN			
	Ltd.	Reg No/Reg Date	SLE3638Y / 02/07/201			
	Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Date In/Mileage	/ 44628			
		Chassis No	KNAF3416MK5048435			
		Engine No	G4FGKH742900			
		Make/Model	KIA/CERATO 1.6 A SX SR G518			
			4SS SILKY SILVER / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
AX00000	Credit	12/07/2021/ 18:10	BLE	261 / Edwin Caina	1	35992			- 55
		Description of Goods	s / Service	5	Qty	Unit Price	Disc%	An	nount
SUPPLY B	DY PNL S	SEALANT						20	30.00
M SUNDRY									30.0
Sundries							400	7	800.0
A 33900099	FD V MEN	MBER , ENGINE & GEARE	OY MOUNT	ING			7		
		/ MIS	DOX PIOURI	ina	1.00	633.00	20.00		506.4
M COVER-FR M CAP-FRON		mis			1.00	9.00	20.00		7.2
M GRILLE-F					1.00	485.00	20.00	/	388.0
		FOG LAMP, LH / mis			1.00	15.00	20.00	1	12.0
		FOG LAMP, RH _ MIJ			1.00	15.00		/ ,	12.0
M LAMP ASS			П		1.00	303.00		4	242.4
M LAMP ASS			\sim	TIPO O	5 7.99	303.00			242.4
MOULDING			511		1.00	216.00	A SECURE		172.8
MOULDING-			S) (C		(4.0C	7 216.00			172.8
		PEATER LH / MI)			1.00	143.00			114.4
		PEATER RH			1.00	143.00			114.4
AIR DUCT	FR BUMPE	R, LH / CR			1.00		20.00	//	11.2
AIR DUCT-			his		1.00	14.00			11.2
		IMPER ENERGY	V. 7		1.00	84.00		/	91.2
STIFFNER-	FR BPR L	wr / cru	00		1.00	114.00		/	17.6
BRACKET-F	R BUMPER	R UPR SIDE MTG	gr gr		1.00	22.00 22.00		/	17.6
		R UPR SIDE MTG	12,		1.00	163.00		/	521.6
ULTRASONI	C SENSOR	(M331-1 1M13 .	is .		4.00	207.00		1	165.6
		IN EXILENCE OF THE	M		1.00	38.00			30.4
GARNISH-R					1.00 1.00	32.00		1	25.0
ORNAMENT-					1.00	2210.00		/	1768.0
LAMP ASSY					1.00	2210.00		/	1768.
LAMP ASSY		/ (NT			1.00	1502.00		1	1201.
PANEL ASS		- 000			1.00	43.00			34.
HINGE ASS					1.00	43.00			34.
HINGE ASS	Y-HOOD,R	H & 15/00			1.00	430.00			344.
PANEL-FEN	DER,LH				1.00		20.00		344.
PANEL-FEN	DED DH	- 01)			1.00	430.00	20.00	1'	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamped party survey is on a "Without Prejudice" basis

the rubber seal or other repair requiring the removal of the windscreen.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would be marked the above estimate is based on our initial inspection and does not include any additional parts or labour which my be required to the computer work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which my be required to the work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before to the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. Page 2 of 3



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info		
	Cust No/Name	/CHEN KAIWEN, KELVIN		
AIG Asia Pacific Insurance Pte.	Reg No/Reg Date	SLE3638Y / 02/07/201		
Ltd. MOTOR CLAIM DEPARTMENT	Date In/Mileage			
78 SHENTON WAY #09-16	Chassis No	KNAF3416MK5048435		
AIG BUILDING	Engine No	G4FGKH742900		
SINGAPORE 079120	Make/Model	KIA/CERATO 1.6 A SX SR G518		
Contact No 64191000		4SS SILKY SILVER / WK SATURN BLACK		

D. C. Company	CSE	Operator		WIP No		1	The second
Account No Terms Date/Time Printed LAX00000 Credit 12/07/2021/ 18:10	BLE	261 / Edwin Caina		35992			
LAX00000 Credit 12/07/2021/ 18:10 Description of Good	The state of the s		Qty I	Jnit Price	Disc%	A	mount
The same of the sa	25 / 001 / 1005		1.00	27.00	20.00		21.60
H INSOLATION TENSEN -			1.00	27.00	20.00		21.60
THE THE TENED TH			1.00	156.00	20.00	/	124.80
M PAD-HOOD INSOCATING			1.00	103.00	20.00		82.40
M LATCH ASSY-HOOD & OT	10		1.00	95.00	20.00		76.00
M GUARD ASSY-FRONT WHEEL, LH M GUARD ASSY-FRONT WHEEL, RH	11		1.00	95.00	20.00	,	76.00
M GUARD ASSY-FRONT WHEEL, LH M GUARD ASSY-FRONT WHEEL, RH M PANEL ASSY-UNDER COVER	•		1.00	117.00	20.00		93.60
			1.00	821.00			656.80
M GLASS-WINDSHIELD & AASS X AA			1.00		20.00	,	44.80
II HOULDING WINDOWN			1.00	247.00	20.00	/,	197.60
M COVER ASSY-COWL TOP CP CK		1	1.00	174.00		<i>'</i> .	139.20
M CLEANER ASSY-AIR (K		imat	1.00		20.00	/	4.00
M DUCT-EXTENSION (R)	(\mathcal{C}_{1})	1100121	1.66	9.00	20.00		7.20
M SHIELD-AIR INTAKE	(S) [L]	111 11 11 (21	14.60-7	55.00	20.00		44.00
M DUCT ASSY-AIR CRY			1.00	115.00	20.00		92.00
M DUCT ASSY-EXTENSION	n		1.00	146.00	20.00		116.80
M RESERVOIR & PUMP ASSY-WASHER X 1	,		1.00	28.00	20.00	/.	22.40
00			1.00	28.00			22.40
M GUARD-AIR, RH / BR M CONDENSER ASSY-COOLER / BT			1.00	687.00		/	549.60
07			1.00	646.00			516.80
M RADIATOR ASSY - OF			1.00		20.00	/	524.80
M BLOWER ASSY CALLED 1 XAA			1.00		20.00		32.00
M HOSE ASST-KADAATOR, LWK	í		1.00		20.00		22.40
M FILLER NECK WOST-KANTATOR			1.00	27.00	and the second second	/	21.60
THOSE ASSISTANCE			1.00	31.00			24.80
HOSE-RADIATOR INLET 1 X 10 X 11			1.00		20.00		85.60
BRACKET ASST-ENGINE SOLL			1.00		20.00		74.40
BRACKET ASSI-ENG HIG			1.00		20.00		166.40
BRACKET ASSY-ENGINE MTG	11		1.00		20.00		163.20
DRACKET ASSITTANISHISSION AND	11.3		1.00		20.00		120.00
BRACKET ASSY-ROLL ROD		12/2/21 2 mm	1.00	1156.00		/	924.80
CROSSMEMBER COMPL		18/1/1/1/2017	1.00	1150.00	20.00	_	924.00
	5	13 7 21, 3-0912 Heve (LKK)					
Confirm & accepted by SURVEYO							
Confirm a accepted by	R SIGNATURE	: 00-14 AL	_	and the second second	tt		25,598.0
	1-1-1	r_!	% GST on	25598.	00		1791.8
DATE :	110	· Me dui	To	tal Payab	le		27,389.8
REMARKS	:	10	_				
uthorized signatory and company stamp						-	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 3