

CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CHEN KAIWEN, KELVIN Reg No/Reg Date SLE3638Y / 02/07/201 Date In/Mileage / 44628 Chassis No KNAF3416MK5048435 Engine No G4FGKH742900 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	12/07/2021/ 18:10	BLE	261 / Edwin Caina	35992
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FR BUMPER, FR SUPPORT, BONNET, LHF FENDER & RHF FENDER	4	400		1600 4000.00
	REPAIR LHF DOOR, RHF DOOR, LHF WHEELHOUSE, RHF WHEELHOUSE, LHF A PILLAR, RHF A PILLAR & BOTH FR CHASSIS				
E PNT98000	RESPRAY FR BUMPER, BONNET, LHF FENDER, LHF WHEELHOUSE, LHF A PILLAR, LHF DOOR, RHF FENDER, RHF WHEELHOUSE, RHF A PILLAR, RHF DOOR & BOTH FR CHASSIS	5	350		1750 4200.00
E PNT88000	RENEW AIRCON CONDENSER & RADIATOR				100.00
M SUNDRY	TOP UP AIRCON GAS				80.00
A 11900199	REMOVE & REFIT ENGINE ASSY & GEARBOX TO GIVE WAY FOR REPAIR				490 800.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000	CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH				1000.00
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment				120.00
E PNT88000	TO RENEW FR WINDSCREEN GLASS				X 240.00
M SUNDRY	INSTALL FR WINDSCREEN SOLAR FILM				X 280.00
M SUNDRY	SUPPLY WINDSCREEN SEALANT				X 80.00
M SUNDRY	SUPPLY FR NUMBER PLATE WITH CASING				50.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				40 80.00
M SUNDRY					40 80.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CHEN KAIWEN, KELVIN Reg No/Reg Date SLE3638Y / 02/07/201 Date In/Mileage / 44628 Chassis No KNAF3416MK5048435 Engine No G4FGKH742900 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	12/07/2021/ 18:10	BLE	261 / Edwin Caina	35992	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
SUPPLY BODY PNL SEALANT						
M SUNDRY						20 30.00
Sundries						?
A 33900099						800.00
TO RENEW FR X-MEMBER , ENGINE & GEARBOX MOUNTING						
M COVER-FR BUMPER	/ MIS		1.00	633.00	20.00	506.40
M CAP-FRONT HOOK	/ MIS		1.00	9.00	20.00	7.20
M GRILLE-FRONT BUMPER	/ MIS		1.00	485.00	20.00	388.00
M COVER-FR BUMPER FOG LAMP,LH	/ MIS		1.00	15.00	20.00	12.00
M COVER-FR BUMPER FOG LAMP,RH	/ MIS		1.00	15.00	20.00	12.00
M LAMP ASSY-FRONT FOG,LH	/ MIS		1.00	303.00	20.00	242.40
M LAMP ASSY-FRONT FOG,RH	/ MIS		1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER,LH	/ MIS		1.00	216.00	20.00	172.80
M MOULDING-FRONT BUMPER,RH	/ MIS		1.00	216.00	20.00	172.80
M LAMP ASSY-SIDE REPEATER,LH	/ MIS		1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER,RH	/ MIS		1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER,LH	/ GR		1.00	14.00	20.00	11.20
M AIR DUCT-FR BUMPER,RH	/ MIS		1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY	/ MIS		1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR	/ CRU		1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG	/ GR		1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG	/ GR		1.00	22.00	20.00	17.60
M ULTRASONIC SENSOR ASSY-P.A.S	/ MIS		4.00	163.00	20.00	521.60
M WIRING ASSY-BUMPER EXTENSION	/ TAL		1.00	207.00	20.00	165.60
M GARNISH-RADIATOR GRILLE	/ MIS		1.00	38.00	20.00	30.40
M ORNAMENT-KIA NO.115	/ MIS		1.00	32.00	20.00	25.60
M LAMP ASSY-HEAD,LH	/ GR		1.00	2210.00	20.00	1768.00
M LAMP ASSY-HEAD,RH	/ CR		1.00	2210.00	20.00	1768.00
M PANEL ASSY-HOOD	/ CR		1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH	/ GR		1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH	/ BT		1.00	43.00	20.00	34.40
M PANEL-FENDER,LH	/ R		1.00	430.00	20.00	344.00
M PANEL-FENDER,RH	/ ON		1.00	430.00	20.00	344.00

Confirm &amp; accepted by


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

and party survey is on a "Without Prejudice" basis

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CHEN KAIWEN, KELVIN Reg No/Reg Date SLE3638Y / 02/07/201 Date In/Mileage / 44628 Chassis No KNAF3416MK5048435 Engine No G4FGKH742900 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	12/07/2021/ 18:10	BLE	261 / Edwin Caina	35992
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M INSULATOR-FENDER LH X		1.00	27.00	20.00	21.60
M INSULATOR-FENDER RH X		1.00	27.00	20.00	21.60
M PAD-HOOD INSULATING X		1.00	156.00	20.00	124.80
M LATCH ASSY-HOOD X		1.00	103.00	20.00	82.40
M GUARD ASSY-FRONT WHEEL, LH		1.00	95.00	20.00	76.00
M GUARD ASSY-FRONT WHEEL, RH		1.00	95.00	20.00	76.00
M PANEL ASSY-UNDER COVER	GR	1.00	117.00	20.00	93.60
M GLASS-WINDSHIELD X		1.00	821.00	20.00	656.80
M MOULDING-WINDSHIELD GLASS X		1.00	56.00	20.00	44.80
M COVER ASSY-COWL TOP	GR	1.00	247.00	20.00	197.60
M CLEANER ASSY-AIR	GR	1.00	174.00	20.00	139.20
M DUCT-EXTENSION	CR	1.00	5.00	20.00	4.00
M SHIELD-AIR INTAKE	CR	1.00	9.00	20.00	7.20
M DUCT ASSY-AIR	CR	1.00	55.00	20.00	44.00
M DUCT ASSY-EXTENSION	GR	1.00	115.00	20.00	92.00
M RESERVOIR & PUMP ASSY-WASHER X		1.00	146.00	20.00	116.80
M GUARD-AIR, LH	mis	1.00	28.00	20.00	22.40
M GUARD-AIR, RH	GR	1.00	28.00	20.00	22.40
M CONDENSER ASSY-COOLER	BT	1.00	687.00	20.00	549.60
M RADIATOR ASSY	BT	1.00	646.00	20.00	516.80
M BLOWER ASSY	GR	1.00	656.00	20.00	524.80
M HOSE ASSY-RADIATOR, LWR		1.00	40.00	20.00	32.00
M FILLER NECK ASSY-RADIATOR		1.00	28.00	20.00	22.40
M HOSE ASSY-RADIATOR, UPR	CR	1.00	27.00	20.00	21.60
M HOSE-RADIATOR INLET		1.00	31.00	20.00	24.80
M BRACKET ASSY-ENGINE SUPT		1.00	107.00	20.00	85.60
M BRACKET ASSY-ENG MTG		1.00	93.00	20.00	74.40
M BRACKET ASSY-ENGINE MTG		1.00	208.00	20.00	166.40
M BRACKET ASSY-TRANSMISSION	MTG	1.00	204.00	20.00	163.20
M BRACKET ASSY-ROLL ROD		1.00	150.00	20.00	120.00
M CROSSMEMBER COMPL		1.00	1156.00	20.00	924.80

Confirm &amp; accepted by

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

REMARKS:

OD-AL AL

Excl-1

P/P, 8 days

Nett

7% GST on

Total Payable

25,598.00

1791.86

27,389.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.