

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007573/EUCN2**Date:** 26/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00084592000
Claimant Vehicle No :	SLQ9381J	Insured Vehicle No :	GBG7058C
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203852/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ9381J	Engine No:	F527H475B38A15A
Make & Model:	BMW X1 SDRIVE18I, 1.5 LED NAV (A)	Chassis No:	WBAHS120605J97076
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	67362 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R18	Rear Tyre Size:	225/50R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,840.90	617.35	2,223.55	78.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,198.00	2,703.00	495.00	15.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,038.90	3,320.35	2,718.55	45.02
+ GST 7.00/7.00% (S\$)	422.72	232.42	190.30	45.02
Nett Amount (S\$)	6,461.62	3,552.77	2,908.85	45.02

INSPECTION

Date of Assignment:	17/08/2021	Performance Motors Limited (Alexandra)
Date Inspected:	17/08/2021 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	3.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2021)
Parts:	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ9381J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH BUMPER MOUNT	Not Necessary	162.25 FS	*- FS
2	1		*RR BUMPER CARRIER	Not Necessary	516.00 FS	*- FS
3	1		*REAR TRIM UNDERRIDE PROTECTION (X1)	Not Necessary	178.25 FS	*- FS
4	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	143.35 FS	*- FS
5	1		*REAR BUMPER PANEL PRIMED	Repair	907.90 FS	*- FS
6	1		*REAR BUMPER MIDDLE TRIM PANE	Not Necessary	266.95 FS	*- FS
7	1		*REAR BUMPER TRIM BOTTOM (LINES)	Cut	232.45 FS	*232.45 FS
8	1		*EXPANDING RIVET BLACK (30 Pcs)	Necessary (23 Pcs only)	42.00 FS	*32.20 FS
9	1		*REAR LH REFLECTOR	Not Necessary	39.05 FS	*- FS
10	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
11	5		*EXPANDING RIVET	Necessary	5.75 FS	*5.75 FS
12	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Cut	266.95 FS	*266.95 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,840.90	617.35
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	986.00
3	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATION (NO STRAIGHT AFTER ACCIDENT)	New	531.00	531.00
Gross Labour Cost (\$\$)			3,198.00	2,703.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >