

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS3/AIG21007574/GRA3Q2

Date:

27/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070129896

Claimant Vehicle No : SKT7411R**Insured Vehicle No :**

GBF3808L

Date of Loss: 10/07/2021

Nature of Claim:

TP

Claim No:

5797707387SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKT7411R**

Make & Model: JAGUAR XF, 2.0 L GTDI (A)

Engine No:

015010200359204PT

Reg. Date: 22/06/2015 (Man. Year: 2015)

Chassis No:

SAJAC05MXFPU73994

Colour: Red

Odometer:

47794 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R18

Rear Tyre Size:

245/45Z R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

7/27/2021

Adjuster Report

Date of Assignment: 13/07/2021

Date Inspected: 14/07/2021 Inspected At:

Kian Teong Auto Centre (HQ)
BLK 176 SIN MING DRIVE #01-08 SIN MING AUTOCARE
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*FRT GRILLE	Cracked	0.00 F	*- F
5	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
6	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
7	1		*FRT APRON PANEL	Cracked	0.00 F	*- F
8	1		*BONNET	Buckled	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >