

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

3,651.00

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 462E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	ABRASION GUA (SN)	NOT NECESSARY	2.70	-
1	ABRASION GUA (SN)	NOT NECESSARY	2.70	-
1	HOLDER I CAM (SN)	NOT NECESSARY	23.30	-
1	REAR BUMPER RH SIDE GUIDE (M) (SN)	CRACKED	193.40	193.40
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	NOT NECESSARY	51.95	-
1	REAR BUMPER PANEL PRIMED (M PDC/ICA (SN)	SCRATCHED	1,191.60	1,191.60
1	REAR BUMPER TRIM PANEL BOTTOM PAINT (SN)	NOT NECESSARY	514.10	-
1	SET MOUNTING PDC/PMA SENSOR REAR (SN)	NOT NECESSARY	61.00	-
24	EXPANDING RIVET WHITE (SN)	NOT NECESSARY	85.20	-
1	REAR RH REAR REFLECTOR (SN)	NOT NECESSARY	39.05	-
10	EXPANDING RIVET BLACK (SN) (ADDITIONAL)	NECESSARY	14.00	14.00
			2,329.00	1,479.00
	<u>LABOUR</u>			
	REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC.		1,275.00	850.00
	PAINTING REAR BUMPER.		1,038.00	986.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	168.00
			2,667.00	2,172.00
	GRAND TOTAL		4,996.00	3,651.00

Report Ref No. CS/SMR21007575/R1uf3e2

MOHAMMED RASUL BIN MOHD YUNUS

**RECOMMENDED COST OF REPAIRS** 

**Automotive Assessor** 

ANG BRYAN TANI

**Automotive Assessor / Investigator**