



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 8967R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	BENT	885.40	845.90
2	TAIL GATE DAMPER	SERVICEABLE	240.00	-
1	TAIL GATE LOCK AND MOTOR	DENTED	285.00	285.00
1	TAIL GATE RUBBER	DISTORTED	189.00	189.00
1	TAIL GATE BADGE JAZZ	NECESSARY	37.80	37.80
1	TAIL GATE W/S GLASS MOULDING	NECESSARY	118.90	118.90
1	REAR PANEL	BENT	341.60	341.60
1	REAR PANEL TOP GARNISH	MTG CRACKED	106.80	106.80
1	REAR BUMPER	BUCKLED	721.00	493.70
2	REAR BUMPER RETAINER	N/S DISTORTED	96.00	48.00
1	TAIL LAMP LEFT	CUT	355.10	282.00
10	REAR BUMPER CLIP	NECESSARY	15.00	15.00
1	REAR REVERSE CAMERA	SERVICEABLE	200.00	-
1	REAR BUMPER LEFT COVER	SERVICEABLE	45.00	-
	LESS 20% DISCOUNT		-	-552.74
			3,636.60	2,210.96
	<u>SPECIAL NETT ITEMS</u>			
4	REAR BUMPER SENSOR (SN)	CUT	450.00	200.00
1	NUMBER PLATE AND CASING (SN)	SERVICEABLE	80.00	-
			530.00	200.00
	<u>LABOUR</u>			
	RUST PROOFING.		100.00	30.00
	TO REMOVE AND REFIT REAR W/S GLASS.		180.00	120.00
	PANEL BEATING.		880.00	600.00
	SPRAY PAINTING.		900.00	600.00
			2,060.00	1,350.00
	GRAND TOTAL		6,226.60	3,760.96

Report Ref No. CS/AGI21007576/Kqf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00
---	--	--	-----------------

Report Ref No. CS/AGI21007576/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.