

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007581/ATCN2**Date:** 31/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00022782100

Claimant Vehicle No : SJF7624D **Insured Vehicle No :** SJN2602H

Date of Loss: 12/07/2021 Nature of Claim: TP Claim No: SNM21D203863/C03/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF7624D**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZC950050

Reg. Date: 10/06/2008 (Man. Year: 2008) Chassis No: NCP815053094

Colour: Blue Odometer: 147768 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15

Front Left Side: ALTIMAX 6 mm Rear Left Side: ALTIMAX 6 mm

Front Right Side: ALTIMAX 6 mm Rear Right Side: ALTIMAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,031.07	4,656.15	9,374.92	66.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,780.00	1,990.00	4,790.00	70.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,811.07	6,646.15	14,164.92	68.06
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	20,811.07	5,300.00	15,511.07	74.53

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 14/07/2021 Inspected At: Ishare Auto Pte. Ltd. (HQ)
8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @
KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2021)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF7624D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR SIDE MIRROR LH	Damaged	480.70 FL	*480.70 FL
2	1		*FRONT DOOR LH	Distorted	1,207.10 FL	*1,085.00 FL
3	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	145.70 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE LH	Cut	274.60 FL	*274.60 FL
5	2		*FRONT DOOR HINGE LH	Not Necessary	171.40 FL	*- FL
6	1		*FRONT DOOR CHECKER LH	Not Necessary	185.70 FL	*- FL
7	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	185.30 FL	*- FL
8	1		*FRONT DOOR FRAME WEATHER STRIP LH	Not Necessary	95.80 FL	*- FL
9	1		*FRONT DOOR GLASS CHANNEL LH	Bent	125.40 FL	*125.40 FL
10	1		*FRONT DOOR INNER LOCK LH	Damaged	398.70 FL	*398.70 FL
11	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	45.10 FL	*- FL
12	1		*FRONT DOOR INNER SPONGE LH	Not Necessary	75.90 FL	*- FL
13	1		*FRONT DOOR INNER TRIM BOARD LH	Cracked	1,586.20 FL	*685.00 FL
14	1		*FRONT DOOR REGULATOR LH	Damaged	287.90 FL	*287.90 FL
15	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	704.60 FL	*- FL
16	1		*FRONT DOOR SPEAKER LH	Not Necessary	326.40 FL	*- FL
17	2		*FRONT DOOR STOPPER LH	Not Necessary	51.40 FL	*- FL
18	1		*FRONT DOOR STEP PANEL INNER GARNISH (OUTER) LH	Not Necessary	145.10 FL	*- FL
19	1		*ROCKER PANEL LH	Not Necessary	485.60 FL	*- FL
20	1		*CENTER PILLAR LH (OUTER)	Not Necessary	397.80 FL	*- FL
21	1		*SLIDING DOOR LH	Dented	1,683.90 FL	*1,250.00 FL
22	1		*SLIDING DOOR STEP PANEL GARNISH LH	Not Necessary	287.60 FL	*- FL
23	1		*SLIDING DOOR STOPPER (BACK) LH	Not Necessary	38.90 FL	*- FL
24	2		*SLIDING DOOR ALIGN STOPPER (FRONT) LH	Not Necessary	78.20 FL	*- FL
25	1		*SLIDING DOOR LOWER ROLLER LH	Damaged	110.80 FL	*110.80 FL
26	1		*SLIDING DOOR LOWER RAILWAY PANEL LH	Not Necessary	288.20 FL	*- FL
27	1		*SLIDING DOOR OUTER STRIP LH	Not Necessary	185.70 FL	*- FL
28	1		*SLIDING DOOR OUTER HANDLE LH	Cut	343.50 FL	*215.00 FL
29	1		*SLIDING DOOR INNER LOCK LH (FRONT)	Damaged	432.90 FL	*432.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*SLIDING DOOR INNER LOCK LH (BACK)	Not Necessary	550.70 FL	*- FL
31	1		*SLIDING DOOR FRAME WEATHERSTRIP LH	Not Necessary	291.20 FL	*- FL
32	1		*SLIDING DOOR INNER TRIM LH	Cracked	1,283.90 FL	*685.00 FL
33	1		*REAR FENDER LH	Repair	984.60 FL	*- FL
34	1		*REAR FENDER ARCH SEAL LH	Necessary	97.20 FL	*97.20 FL
35	1		*REAR FENDER INNER PANEL LH	Repair	397.10 FL	*- FL
36	1		*REAR SHOCK ABSORBER LH	Not Necessary	331.10 FL	*- FL
37	1		*REAR WHEEL HUP WITH BEARING LH	Not Necessary	946.20 FL	*- FL
38	1		*SET FRONT DOOR INNER TRIM BOARD CLIP LH	Necessary	80.00 FS	*30.00 FS
39	1		*SET FRONT DOOR STEP PANEL INNER GARNISH (OUTER) CLIP LH	Not Necessary	60.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
41	1		*SET SLIDING DOOR STEP PANEL GARNISH CLIP LH	Not Necessary	60.00 FS	*- FS
42	1		*SET SLIDING DOOR INNER TRIM CLIP LH	Necessary	80.00 FS	*30.00 FS
43	1		*REAR FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
44	1		*SET REAR FENDER COWLING COWLING CLIP LH	Not Necessary	80.00 FS	*- FS
45	1		*REAR FENDER GLASS SEALANT LH	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER GLASS INNER SEAL LH	Not Necessary	60.00 FS	*- FS
47	1		*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	80.00 FS	*- FS
48	1		*REAR WHEEL RIM LH	Not Necessary	850.00 FS	*- FS
49	1		*REAR WHEEL TYRE LH	Not Necessary	480.00 FS	*- FS
50	1		*SIDE ANGLE MIRROR (SPECIAL TYPE)	Not Necessary	80.00 FS	*- FS
51	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,958.10	6,188.20
- List Item Discount on L Items 25.00/25.00% (\$)	3,927.03	1,532.05
Total Parts (\$)	14,031.07	4,656.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	1,800.00	900.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	TRANFER FRONT DOOR MECHANISM LH	New	80.00	40.00
7	REMOVE & REFIX AUDIO SPEAKER LH	New	250.00	0.00
8	REMOVE & REINSTALL FRONT WINDOW GLASS LH	New	120.00	40.00
9	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	0.00
11	TRANSFER REAR SLIDING DOOR MECHANISM LH	New	80.00	60.00
12	REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT	New	100.00	0.00
13	REMOVE AND REFIX REAR FENDER GLASS LH	New	100.00	0.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	0.00
15	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
16	RESET ABS LIGHT	New	350.00	0.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			6,780.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >