

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007583/AGA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900150720
Claimant Vehicle No :	SFB188K	Insured Vehicle No :	SMP1897J
Date of Loss:	08/07/2021	Nature of Claim:	TP
		Claim No:	1924987775SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFB188K		
Make & Model:	BMW 540i, 3.0 SR LED NAV HUD RCP MSPORT (A)	Engine No:	11825667B58B30A
Reg. Date:	15/07/2019 (Man. Year: 2019)	Chassis No:	WBAJB32070WW42402
Colour:	Blue	Odometer:	27386 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	245/35 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,557.00	2,354.00	5,203.00	68.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	640.00	380.00	37.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,577.00	2,994.00	5,583.00	65.09
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	8,577.00	2,400.00	6,177.00	72.02
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/07/2021	
Date Inspected:	12/07/2021	Inspected At: ADVANCE AUTO GARAGE (#03-01) (HQ) 10 Kaki Bukit Road 2 #03-01, First East Centre, Singapore 417868
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,653.00 F	*1,653.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Not Necessary	68.00 F	*- FL
4	1		*FRONT BUMPER FOG LAMP RH	Cracked	372.00 F	*372.00 FL
5	1		*FRONT BUMPER FOG LAMP COVER RH	Cracked	98.00 F	*98.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER GARNISH RH	Cracked	55.00 F	*55.00 FL
7	1		*FRONT BUMPER SENSOR	Damaged	382.00 F	*382.00 FL
8	1		*HEADLAMP RH	Not Necessary	4,879.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,557.00	2,610.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	256.00
Total Parts (\$\$)	7,557.00	2,354.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	100.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	120.00	60.00
Gross Labour Cost (\$\$)			1,020.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >