

Advance

TP AIG

Jaslin

SFB188K 2019 July

Bmw 540i 2998cc

WBAJB32070WW42402

Front Bumper Deformed 1653 ✓
50(SN) ✓

Front Bumper clips x2

Front Bumper Side Holder RH. x2 68 +

Front Bumper Fog Lamp RH. ~~could~~ 372 ✓

Front Bumper Fog Lamp Cover RH. ~~could~~ 98 ✓

Front Bumper Fog Lamp Cover Garnish RH. ~~could~~ 55 ✓

Front Bumper Sensor Damaged 382 ✓

Headlamp RH. x2 4879 x

2560
2304 SN: 50

Panel Beating

Spray Painting

Wiring

To remove front bumper sensor 120.60

total: 2994

L/S: 2.4K

03 Days

2.4K

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: