



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 1828P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S FRONT DOOR	BENT	3,800.00	1,824.10
1	N/S FRONT DOOR REGULATOR	DISTORTED	700.00	700.00
1	N/S REAR DOOR	BENT	4,350.00	1,901.30
1	N/S REAR DOOR REGULATOR	DISTORTED	900.00	900.00
2	N/S DOOR HINGE @\$180.00	TO REPAIR SEE LABOUR	360.00	-
1	N/S REAR DOOR CHECK	SERVICEABLE	170.00	-
1	N/S SIDE SKIRT	DENTED / CRACKED	2,150.00	1,320.80
1	N/S FRONT WHEEL RIM	DENTED	2,550.00	2,050.00
	LESS 10% DISCOUNT		-1,498.00	-869.62
			13,482.00	7,826.58
1	N/S FRONT DOOR RUBBER (50%)(SN)	NECESSARY	375.00	187.50
1	N/S REAR DOOR RUBBER (50%)(SN)	NECESSARY	375.00	187.50
	LESS 10% DISCOUNT		-75.00	-
			675.00	375.00
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT.		1,200.00	1,000.00
	TO CHECK WHEEL ALIGNMENT.		80.00	60.00
	TO TRANSFER DOOR FITTING.		100.00	100.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF N/S DOOR HINGE.		800.00	600.00
			2,180.00	1,760.00
GRAND TOTAL			16,337.00	9,961.58

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,950.00
---	--	--	-----------------

Report Ref No. CS/AGI21007587/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.