

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007589/APA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900160857
Claimant Vehicle No :	SFE8287P	Insured Vehicle No :	SMP693L
Date of Loss:	09/07/2021	Nature of Claim:	TP
		Claim No:	5794848116SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFE8287P	Engine No:	R18A1728839
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61025442
Reg. Date:	12/04/2007 (Man. Year: 2007)	Odometer:	242478 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,002.40	2,814.40	5,188.00	64.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,210.00	1,760.00	44.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,972.40	5,024.40	6,948.00	58.03
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,972.40	4,000.00	7,972.40	66.59
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,756.45		

INSPECTION

Date of Assignment:	13/07/2021	Ace Autolution Pte Ltd (KAKI BUKIT)
Date Inspected:	13/07/2021 Inspected At:	13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Estimated Period of Repair:	6.0 days	Singapore 417807

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,171.30 FL	*903.00 FL
2	1		*REAR TAILGATE LOCK	Damaged	135.00 FL	*135.00 FL
3	1		*REAR TAILGATE LOCK CATCH	Not Necessary	84.00 FL	*- FL
4	2		*REAR TAILGATE DAMPER LH & RH	Not Necessary	600.00 FL	*- FL
5	1		*REAR TAILGATE WEATHERSTRIP	Cut	150.90 FL	*150.90 FL
6	1		*REAR TAILGATE STREAM EMBLEM	Necessary	70.00 FL	*45.00 FL
7	1		*REAR TAILGATE LOGO	Not Necessary	80.00 FL	*- FL
8	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	95.00 FL	*- FL
9	1		*REAR TAILGATE INNER BOARD	Not Necessary	320.00 FL	*- FL
10	1		*REAR TAILGATE UPPER GARNISH	Not Necessary	165.80 FL	*- FL
11	2		*REAR TAILGATE NUMBER PLATE LAMP LH & RH	Not Necessary	202.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	910.00 FL	*688.00 FL
13	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	182.00 FL	*70.00 FL
14	1		*REAR BUMPER TOW HOCK COVER	Deformed	95.00 FL	*35.00 FL
15	2		*REAR TAILLAMP LH & RH	Not Necessary	1,450.00 FL	*- FL
16	1		*REAR END PANEL INNER	Dented	575.00 FL	*315.00 FL
17	1		*REAR END PANEL OUTER	Dented	459.00 FL	*459.00 FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	175.00 FL	*175.00 FL
19	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	770.40 FL	*- FL
20	1		*REAR EXHAUST SILENCER	Not Necessary	998.00 FL	*- FL
21	2		*REAR EXHAUST SILENCER MOUNTING	Not Necessary	110.00 FL	*- FL
22	1		*REAR WINDSCREEN SEAL	Necessary	92.10 FL	*92.10 FL
23	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
24	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
25	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
26	1		*SET REAR TAILGATE INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
28	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	120.00 FS	*- FS
29	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
30	1		*SET REAR CAR PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,780.50	3,428.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,778.10	613.60
Total Parts (\$)	8,002.40	2,814.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIR AND REPLACE DAMAGED PARTS	New	1,600.00	1,000.00
2	TO SUPPLY PAINT MATERIALS ,EXPADDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	850.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	80.00
5	TO REMOVE /REFIT WINDSCREEN	New	150.00	120.00
6	TO TRANSFER BOOTLID MECHANISM	New	100.00	80.00
7	TO REMOVE AND REFIX REAR CAR SEAT	New	210.00	0.00
8	TO REMOVE AND REPLACE REVERSE SENSOR AND TEST	New	100.00	50.00
9	TO CONDUCT WATER SEEPAGE TEST	New	100.00	0.00
10	TO REMOVE AND REPLACE EXHAUST SILENCER	New	180.00	0.00
Gross Labour Cost (\$)			3,970.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >