

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007593/EVF3E2

Date: 30/07/2021

REFERENCE

Insured/Claimant: RODRIGUES JACQUELINE MARY
Date of Loss: 11/07/2021

Policy No: 2070112047
Nature of Claim: OD Claim No: 6727348501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU630S	Engine No:	G3LCLP069907
Make & Model:	KIA STONIC, 998cc (A)	Chassis No:	KNAD6811VL6457844
Reg. Date:	28/07/2020 (Man. Year: 2020)	Odometer:	6823 km
Colour:	Grey		
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Continental 4 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 4 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,518.00	8,198.00	3,320.00	28.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	2,420.00	1,150.00	32.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,088.00	10,618.00	4,470.00	29.63
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,788.00	10,318.00	4,470.00	30.23
+ GST 7.00/7.00% (S\$)	1,035.16	722.26	312.90	30.23
Nett Amount (S\$)	15,823.16	11,040.26	4,782.90	30.23

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 13/07/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER UPR	Dented	476.00 F	*476.00 FL
4	1		*COVER-FR BUMPER, LWR	Broken	367.00 F	*367.00 FL
5	1		*SKID PLATE-FR BUMPER	Not Necessary	55.00 F	*- FL
6	1		*GRILLE-FRONT BUMPER	Broken	96.00 F	*96.00 FL
7	1		*GRILLE ASSY-RADIATOR	Not Necessary	324.00 F	*- FL
8	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 F	*61.00 FL
9	1		*STRIP-FR BUMPER	Not Necessary	27.00 F	*- FL
10	1		*COVER-RADIATOR GRILLE UPR	Broken	46.00 F	*46.00 FL
11	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 F	*98.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	123.00 F	*- FL
13	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	64.00 F	*- FL
14	1		*COVER-FR BUMPER FOG LAMP, LH	Not Necessary	64.00 F	*- FL
15	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 F	*- FL
16	1		*BRACKET-FR BUMPER SIDE, RH	Not Necessary	13.00 F	*- FL
17	1		*BRACKET-FR BUMPER SIDE, LH	Not Necessary	13.00 F	*- FL
18	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	234.00 F	*- FL
19	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	234.00 F	*- FL
20	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	38.00 F	*- FL
21	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	38.00 F	*- FL
22	1		*PANEL ASSY-HOOD	Dented	904.00 F	*904.00 FL
23	1		*BEAM COMPLETE-FR BUMPER	Dented	544.00 F	*544.00 FL
24	1		*CARRIER ASSY-FRONT END MODULE	Broken	556.00 F	*556.00 FL
25	1		*LAMP ASSY-HEAD, RH	Broken	1,845.00 F	*1,845.00 FL
26	1		*LAMP ASSY-HEAD, LH	Broken	1,845.00 F	*1,845.00 FL
27	1		*GUARD-AIR RADIATOR, UPR	Broken	23.00 F	*23.00 FL
28	1		*GUARD-AIR, RH	Broken	14.00 F	*14.00 FL
29	1		*CONDENSER ASSY-COOLER	Dented	648.00 F	*648.00 FL
30	1		*RADIATOR ASSY	Dented	584.00 F	*584.00 FL
31	1		*INSULATOR-RADIATOR MTG, LWR	Not Necessary	8.00 F	*- FL
32	1		*BRACKET ASSY-RADIATOR MTG, UPR	Not Necessary	21.00 F	*- FL
33	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 F	*26.00 FL
34	1		*BLOWER ASSY (Supplementary)	Broken	536.00 F	*536.00 FL
35	1		*INTERCOOLER (Supplementary)	Dented	627.00 F	*627.00 FL
36	1		*AIR GUIDE-INTERCOOLER (Supplementary)	Broken	32.00 F	*32.00 FL
37	10		*CLIP (Supplementary)	Necessary	10.00 F	*10.00 FL
38	1		*ORNAMENT-KIA NO 115 (Supplementary)	Necessary	32.00 F	*32.00 FL
39	1		*WHEEL ASSY-ALUMINIUM (Supplementary)	Cut	790.00 F	*790.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,518.00	10,230.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,032.00
Total Parts (\$\$)	11,518.00	8,198.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT SUPPORT PANEL, BONNET, REPAIR FRT FENDER RH & LH	New	1,200.00	800.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH	New	1,400.00	700.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
6	TRANSFER FRT RIGHT RIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	SUPPLY ONE PC LICENSE PLATE (Supplementary) (Repeated)	New	50.00	0.00
9	RENEW FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
10	REMOVE & INSTALL AIRCON & RADIATOR (Supplementary)	New	100.00	100.00
11	VACCUM AND TOP UP A/C GAS (Supplementary)	New	80.00	80.00
Gross Labour Cost (\$\$)			3,570.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >