



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



GST Reg No : MR-8500111-X

Co Reg No : 199405410K

### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
RODRIGUES JACQUELINE MARY MRS JACQUELINE MARY CHAIN 104 LENGKONG TIGA #02-371 SINGAPORE 410104	Cust No/Name LCV12556/RODRIGUES JACQUELINE MARY MRS J Reg No/Reg Date SMU630S / 28/07/202 Date In/Mileage / 0 Chassis No KNAD6811VL6457844 Engine No G3LCLP069907 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim URG URBAN GREEN / WK SATURN BLACK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LCV12556	CRDVCH	13/07/2021/ 14:58	BLC	881 / Jojo Cheng	36035				
Description of Goods / Services									
E PNT88000						2 x 400			800 1200.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, BONNET,									700 1400.00
REPAIR FRT FENDER RH & LH									120.00
E PNT98000						2 x 350			30.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH									120.00
B WHEELALIGNMENT									50.00
To Conduct Computerize Full Wheel Alignment									40.00
A 90000001									30.00
CHECK WIRING & ELECTRICAL SYSTEM									20.00
A 10028901									476.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM									367.00
M SUNDRY									55.00
FRT NUMBER PLATE WITH FRAME									96.00
M SUNDRY									324.00
APPLY SEALANT FOR ACCIDENT PORTION									61.00
M SUNDRY									27.00
TRANSFER FRT RIGHT RIM									46.00
M SUNDRY									98.00
Sundry						1.00	476.00	00.00	123.00
M COVER-FR BUMPER UPR						1.00	367.00	00.00	64.00
M COVER-FR BUMPER, LWR						1.00	55.00	00.00	64.00
M SKID PLATE-FR BUMPER						1.00	96.00	00.00	32.00
M GRILLE-FRONT BUMPER						1.00	324.00	00.00	13.00
M GRILLE ASSY-RADIATOR						1.00	61.00	00.00	
M MOULDING-FRONT BUMPER A/INTAKE						1.00	27.00	00.00	
M STRIP-FR BUMPER						1.00	46.00	00.00	
M COVER-RADIATOR GRILLE UPR						1.00	98.00	00.00	
M ABSORBER-FRONT BUMPER ENERGY						1.00	123.00	00.00	
M STIFFNER-FR BPR LWR						1.00	64.00	00.00	
M COVER-FR BUMPER FOG LAMP, RH						1.00	64.00	00.00	
M COVER-FR BUMPER FOG LAMP, LH						1.00	32.00	00.00	
M LIP ASSY-FRONT BUMPER						1.00	13.00	00.00	
M BRACKET-FR BUMPER SIDE, RH									

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
RODRIGUES JACQUELINE MARY MRS JACQUELINE MARY CHAIN 104 LENGKONG TIGA #02-371 SINGAPORE 410104  Contact No	Cust No/Name LCV12556/RODRIGUES JACQUELINE MARY MRS J Reg No/Reg Date SMU630S / 28/07/202 Date In/Mileage / 0 Chassis No KNAD6811VL6457844 Engine No G3LCLP069907 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV12556	CRDVCH	13/07/2021/ 14:58	BLC	881 / Jojo Cheng	36035

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET-FR BUMPER SIDE, LH	1.00	13.00	00.00	13.00
M LAMP ASSY-FRONT FOG, RH	1.00	234.00	00.00	234.00
M LAMP ASSY-FRONT FOG, LH	1.00	234.00	00.00	234.00
M AIR DUCT-FR BUMPER, RH	1.00	38.00	00.00	38.00
M AIR DUCT-FR BUMPER, LH	1.00	38.00	00.00	38.00
M PANEL ASSY-HOOD	1.00	904.00	00.00	904.00
M BEAM COMPLETE-FR BUMPER	1.00	544.00	00.00	544.00
M CARRIER ASSY-FRONT END MODULE	1.00	556.00	00.00	556.00
M LAMP ASSY-HEAD, RH	1.00	1845.00	00.00	1845.00
M LAMP ASSY-HEAD, LH	1.00	1845.00	00.00	1845.00
M GUARD-AIR RADIATOR, UPR	1.00	23.00	00.00	23.00
M GUARD-AIR, RH	1.00	14.00	00.00	14.00
M CONDENSER ASSY-COOLER	1.00	648.00	00.00	648.00
M RADIATOR ASSY	1.00	584.00	00.00	584.00
M INSULATOR-RADIATOR MTG, LWR	1.00	8.00	00.00	8.00
M BRACKET ASSY-RADIATOR MTG, UPR	1.00	21.00	00.00	21.00

Steve (LKK) 00-NM AL  
13/7/21, 4.00pm EXCISE -?  
PIP  
My Bel sy  
5 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by [Signature] No illegal modification(s) is allowed  
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

7% GST on **Nett** 12,405.00  
12405.00 868.35  
**Total Payable** 13,273.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.