



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
RODRIGUES JACQUELINE MARY MRS JACQUELINE MARY CHAIN 104 LENGKONG TIGA #02-371 SINGAPORE 410104 Contact No	Cust No/Name LCV12556/RODRIGUES JACQUELINE MARY MRS J Reg No/Reg Date SMU630S / 28/07/202 Date In/Mileage / 0 Chassis No KNAD6811VL6457844 Engine No G3LCLP069907 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV12556	CRDVCH	13/07/2021/ 14:58	BLC	881 / Jojo Cheng	36035		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT SUPPORT PANEL, BONNET, REPAIR FRT FENDER RH & LH				2 x 400			800 1200.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH				2 x 350			700 1400.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							120.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY FRT NUMBER PLATE WITH FRAME							50.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION							40.00
M SUNDRY TRANSFER FRT RIGHT RIM							30.00
M SUNDRY Sundry							20.00
M	COVER-FR BUMPER UPR	1.00	476.00	00.00	476.00		
M	COVER-FR BUMPER,LWR	1.00	367.00	00.00	367.00		
M	SKID PLATE-FR BUMPER	1.00	55.00	00.00	55.00		
M	GRILLE-FRONT BUMPER	1.00	96.00	00.00	96.00		
M	GRILLE ASSY-RADIATOR	1.00	324.00	00.00	324.00		
M	MOULDING-FRONT BUMPER A/INTAKE	1.00	61.00	00.00	61.00		
M	STRIP-FR BUMPER	1.00	27.00	00.00	27.00		
M	COVER-RADIATOR GRILLE UPR	1.00	46.00	00.00	46.00		
M	ABSORBER-FRONT BUMPER ENERGY	1.00	98.00	00.00	98.00		
M	STIFFNER-FR BPR LWR	1.00	123.00	00.00	123.00		
M	COVER-FR BUMPER FOG LAMP,RH	1.00	64.00	00.00	64.00		
M	COVER-FR BUMPER FOG LAMP,LH	1.00	64.00	00.00	64.00		
M	LIP ASSY-FRONT BUMPER	1.00	32.00	00.00	32.00		
M	BRACKET-FR BUMPER SIDE,RH	1.00	13.00	00.00	13.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
RODRIGUES JACQUELINE MARY MRS JACQUELINE MARY CHAIN 104 LENGKONG TIGA #02-371 SINGAPORE 410104 Contact No	Cust No/Name LCV12556/RODRIGUES JACQUELINE MARY MRS J Reg No/Reg Date SMU630S / 28/07/202 Date In/Mileage / 0 Chassis No KNAD6811VL6457844 Engine No G3LCLP069907 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV12556	CRDVCH	13/07/2021/ 14:58	BLC	881 / Jojo Cheng	36035			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-FR BUMPER SIDE, LH				1.00	13.00	00.00	13.00
M	LAMP ASSY-FRONT FOG, RH				1.00	234.00	00.00	234.00
M	LAMP ASSY-FRONT FOG, LH				1.00	234.00	00.00	234.00
M	AIR DUCT-FR BUMPER, RH				1.00	38.00	00.00	38.00
M	AIR DUCT-FR BUMPER, LH				1.00	38.00	00.00	38.00
M	PANEL ASSY-HOOD				1.00	904.00	00.00	904.00
M	BEAM COMPLETE-FR BUMPER				1.00	544.00	00.00	544.00
M	CARRIER ASSY-FRONT END MODULE				1.00	556.00	00.00	556.00
M	LAMP ASSY-HEAD, RH				1.00	1845.00	00.00	1845.00
M	LAMP ASSY-HEAD, LH				1.00	1845.00	00.00	1845.00
M	GUARD-AIR RADIATOR, UPR				1.00	23.00	00.00	23.00
M	GUARD-AIR, RH				1.00	14.00	00.00	14.00
M	CONDENSER ASSY-COOLER				1.00	648.00	00.00	648.00
M	RADIATOR ASSY				1.00	584.00	00.00	584.00
M	INSULATOR-RADIATOR MTG, LWR				1.00	8.00	00.00	8.00
M	BRACKET ASSY-RADIATOR MTG, UPR				1.00	21.00	00.00	21.00

Estimate

Steve (LKK) 00-M1 AL
13/7/21, 4.00pm EXCISE -?
PIPMy Bel sy
5 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by

No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

7% GST on **12405.00** **868.35**
Nett 12,405.00
Total Payable 13,273.35

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.