

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 8680L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HOUSING SUB-ASSY,HEADLAMP,RH (SN)	NOT NECESSARY	6,185.20	-
1	MOULDING,RADIATOR (SN)	CUT	375.80	375.80
1	STAY,FR BUMPER (SN)	NOT NECESSARY	58.00	-
1	STAY,FR BUMPER (SN)	NOT NECESSARY	58.00	-
1	ABSORBER,FR BUMPER (SN)	NOT NECESSARY	155.90	-
1	SEAL,RADIATOR (SN)	NECESSARY	101.50	101.50
1	COVER,FR BUMPER (SN)	NOT NECESSARY	968.20	-
1	COVER,FOG LAMP,RH (SN)	NOT NECESSARY	143.30	-
1	GRILLE SUB-ASSY (SN)	NOT NECESSARY	885.70	-
1	BRACKET,FR BUMPER (SN)	BROKEN	143.20	143.20
2	CLIP (SN)	NECESSARY	3.60	3.60
2	RETAINER,FR FENDER (SN)	NECESSARY	24.80	24.80
2	RETAINER,ULTRASONIC (SN)	NECESSARY	32.80	32.80
2	CLIP,ULTRASONIC (SN)	NECESSARY	8.80	8.80
1	SENSOR,ULTRASONIC (SN)	NOT NECESSARY	490.80	-
1	SUNDRIES (SN)	NECESSARY	80.00	50.00
			9,715.60	740.50
	<u>LABOUR</u>			
	CHECK WIRING SYSTEM AND FOCUS HEADLAMP.		216.50	216.50
	REMOVE/REFIX FRONT PARKING SENSORS.		216.50	216.50
	REMOVE/REFIX FRONT BUMPER COVER AND REALIGN.		1,082.50	866.00
	SPRAY PAINT ON FRONT BUMPER COVER.		927.50	742.00
	TO RESET ECU & REPROGRAMME.		216.50	216.50
	SUPPLY REGN PLATE (PO#) FRONT.		96.00	96.00
			2,755.50	2,353.50
	GRAND TOTAL		12,471.10	3,094.00



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 3,094.00
--------------------------------------

Report Ref No. CS/SMR21007594/Euf3n2



Automotive Assessor



**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**