



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET CERVELO FRAME	CRACKED	3,800.00	3,800.00
1	SET ULTEGRA GROUP (DI2)	DISTORTED	3,200.00	3,200.00
1	ROTOR AND ROTOR CRANK ARM	BENT	700.00	700.00
1	ZIPP 404 CARBON RIMS	CUT	1,400.00	1,400.00
1	ZIPP 808 CARBON RIMS	CUT	1,800.00	1,800.00
1	ZIPP 808 CERAMIC HUB AND BEARINGS	JAMMED	380.00	380.00
1	CHAINRING	DISTORTED	90.00	90.00
1	SADDLE	TORN	330.00	330.00
1	HANDLEBAR-INTERGRATED	BENT	600.00	600.00
1	GARMIN BIKE COMPUTER	DAMAGED	380.00	380.00
1	HELMET-TT	CRACKED	320.00	320.00
1	SPD SHOE	CUT	290.00	290.00
1	LOOK SPD	BROKEN	280.00	280.00
			13,570.00	13,570.00
	<u>LABOUR</u>			
	TO REPLACE ABOVE PARTS AND REWIRE COMPUTER WIRES TO HANDLR BAR.		250.00	200.00
			250.00	200.00
	GRAND TOTAL		13,820.00	13,770.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,000.00

Report Ref No. CS/CTI21007595/Gqce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.