

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|----------------|-------|----------------------|--|
| | CHINA TAIPING IN | ISURANCE (S) PTE LTD | | Ref: | CS/CTI21007595/Gqce2 | |
| | 3 ANSON ROAD # SPRINGLEAF TOV | 16-00 VERSINGAPORE 079909 | | Date: | 10/08/2021 | |
| | | | | Code: | CTI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLP 3505P | Veh. Inspected | | BICYCLE | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | SNM21D203865/C02/SLP3505 P/THAMYL | Excess (\$) | | 0.00 | |
| | Assign From | PAULINE THAM | Assign Date | | 13/07/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | CERVELO P2 | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2018 | |
| | Chassis No. | SNP2D17E00119 | Colour | | WHITE | |
| | Odometer | - | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | FAIR | | | | |
| 3. | Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 700CX25 | ZIPP | | 1 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 700CX25 | ZIPP | | 1 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 10/07/2021 | Inspection Dat | е | 13/07/2021 | |
| | Survey held at | held at 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY | | | | |
| | Repairer | R C AUTO | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | | |
| | ESTIMATED NORI | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | |