

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21007599/R1uf3e2	
	300 BEACH ROAD		Date	e: 23/07/2021	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555	Cod	e: LPC2	
4		Daliau Dartiaulana			
1.	lu a cons d Mala	Policy Particulars	FBH 2411T		
	Insured Veh.	GZ 9354A	Veh. Inspected		
	Policy No.	00/04/04/\\000/004700	Coverage (\$)	0.00	
	Claim No.	20/21/21/VC00/024706	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	13/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA	c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour	MULTI COLOUR	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	80/90-18	GOLDEN BOY	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	3.60-18	GOLDEN BOY	4 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S			
5.	General Information				
	Accident Date	26/06/2021	Inspect Date / Time	14/07/2021 (01:25 PM)	
	Survey held at	AH HWA MOTOR SERVICING			
		1016 YISHUN INDUSTRIAL PARK A, #01-228, YISHUN INDUSTRIAL PARK A, SINGAPORE 768758			
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21007599/R1uf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$