

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007600/AVCN2**Date:** 23/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00029242100
Claimant Vehicle No :	SME8870Y	Insured Vehicle No :	SJC2810G
Date of Loss:	03/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203838/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME8870Y		
Make & Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	HR16932984C
Reg. Date:	20/10/2018 (Man. Year: 2018)	Chassis No:	MNTBBAB17Z0033217
Colour:	Blue	Odometer:	25289 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,971.10	6,141.19	5,829.91	48.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,500.00	1,290.00	46.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,761.10	7,641.19	7,119.91	48.23
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	14,761.10	6,100.00	8,661.10	58.68
+ GST 7.00/7.00% (S\$)	1,033.28	427.00	606.28	58.68
Nett Amount (S\$)	15,794.38	6,527.00	9,267.38	58.68

INSPECTION

Date of Assignment:	13/07/2021	
Date Inspected:	13/07/2021 Inspected At:	ONE GARAGE PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #03-33 PREMIER @ K. BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Aug 2021)

Parts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SME8870Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	653.70 F	*653.70 FL
2	2		*FRONT BUMPER SIDE HOLDER	Damaged	64.20 F	*64.20 FL
3	1		*FRONT BUMPER SPONGE	Cracked	240.60 F	*240.60 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	561.90 F	*561.90 FL
5	2		*FRONT BUMPER REINFORCEMENT STAY	Bent	421.80 F	*421.80 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	255.30 F	*- FL
7	1		*FRONT BUMPER FOG LAMP	O/s Cracked	632.80 F	*316.40 FL
8	1		*FRONT BUMPER FOG LAMP COVER	O/s Deformed	224.40 F	*112.20 FL
9	1		*FRONT BUMPER UNDERCOVER	Deformed	238.40 F	*238.40 FL
10	1		*FRONT GRILLE	Cracked	548.30 F	*548.30 FL
11	1		*FRONT GRILLE LOGO	Necessary	23.50 F	*23.50 FL
12	2		*HEADLAMP	Cracked	1,630.00 F	*1,630.00 FL
13	1		*FRONT SUPPORT PANEL (COMPLETE)	Distorted	669.60 F	*669.60 FL
14	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	307.40 F	*307.40 FL
15	1		*BONNET	Not Necessary	945.80 F	*- FL
16	1		*BONNET LOCK	Not Necessary	55.60 F	*- FL
17	1		*AIR CON CONDENSER	Not Necessary	864.40 F	*- FL
18	2		*AIR CON CONDENSER GUIDE	Cracked	76.00 F	*76.00 FL
19	1		*RADIATOR	Not Necessary	994.80 F	*- FL
20	1		*AIR RESONATOR BOX	Cracked	258.90 F	*258.90 FL
21	1		*WIPER WASHER TANK	Deformed	256.20 F	*256.20 FL
22	1		*WIPER WASHER TANK MOTOR	Not Necessary	85.30 F	*- FL
23	2		*FRONT FENDER	Not Necessary	1,170.40 F	*- FL
24	2		*FRONT FENDER INNER SHIELD	Not Necessary	251.80 F	*- FL
25	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*30.00 FS
26	1		*FRONT NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS
27	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*FRONT BUMPER SENSOR	Damaged	280.00 FS	*200.00 FS
29	1		*FRONT BUMPER UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
30	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
31	1		*FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
33	1		*COOLANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,971.10	6,779.10
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	637.91
Total Parts (S\$)	11,971.10	6,141.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	50.00	30.00
4	TO REMOVE AIR CON CONDENSER AND TO TOP UP AIR CON GAS	New	120.00	60.00
5	TO REMOVE RADIATOR AND TO TOP UP COOLANT	New	120.00	60.00
6	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
Gross Labour Cost (\$)			2,790.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >