



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105426

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 02/08/2021
Reference CC4/FCI21007601/Uea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. CB 6806G
Insured Veh. SG 5920A
Claim No. D21001977MFBP/1
Policy No. D-20096309MFBP
Accident Date 01/07/2021
Inspection Date 14/07/2021

Description	Total
Survey Inspection	234.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	234.00
GST (7%)	16.38
Grand Total	250.38

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21007601/Uea3q2	
			Date: 02/08/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 5920A	Veh. Inspected	CB 6806G
	Policy No.	D-20096309MFBP	Coverage (\$)	0.00
	Claim No.	D21001977MFBP/1	Excess (\$)	0.00
	Assign From	JACLYN	Assign Date	13/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE HIROOF (A)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JTFST22PX00011570	Colour	SILVER
	Odometer	359663 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	MICHELIN	6 mm
	L/H Front Tyre	195 R15	MICHELIN	6 mm
	R/H Rear Tyre	195 R15	MICHELIN	6 mm
	L/H Rear Tyre	195 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/07/2021	Inspection Date	14/07/2021
	Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD BLK 8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT (GATE 1) #02-54/55 SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 6806G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WING MIRROR ASSEMBLY LH	BROKEN	1,197.10	1,197.10
1	FRONT DOOR GLASS LH	CUT	589.50	515.00
	LESS 25% DISCOUNT		-446.65	-428.03
			1,339.95	1,284.07
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR LH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
			-	-
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH.		400.00	100.00
	SPRAY PAINT ON THE AFFECTED AREAS .		400.00	200.00
	ANTI-RUST COATING.	NOT NECESSARY	50.00	-
			850.00	300.00
	GRAND TOTAL		2,189.95	1,584.07
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CC4/FCI21007601/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 6806G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 6806G

RE-INSPECTION

