



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107563

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 03/11/2021  
Reference CC4/FCI21007602/Kra3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SMN 8397A  
Insured Veh. YN 9201H  
Claim No. D21002024MFCV/1  
Policy No. D-21097378MFCV  
Accident Date 11/07/2021  
Inspection Date 13/07/2021

Description	Total
Survey Inspection	304.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>304.00</b>
<b>GST (7%)</b>	<b>21.28</b>
<b>Grand Total</b>	<b>325.28</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21007602/Kra3q2 Date: 03/11/2021 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 9201H	Veh. Inspected	SMN 8397A	
Policy No.	D-21097378MFCV	Coverage (\$)	0.00	
Claim No.	D21002024MFCV/1	Excess (\$)	0.00	
Assign From	VIC	Assign Date	13/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MR2B23F3301183676	Colour	METALLIC GREY	
Odometer	196641 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WEST LAKE	8 mm	
L/H Front Tyre	185/60 R15	WEST LAKE	8 mm	
R/H Rear Tyre	185/60 R15	WEST LAKE	8 mm	
L/H Rear Tyre	185/60 R15	WEST LAKE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/07/2021	Inspection Date	13/07/2021	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 8397A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	CRACKED	495.70	495.70
2	FRONT BUMPER RETAINER @\$100.40	N/S DISTORTED	200.80	100.40
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	399.50	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	269.50	-
1	LH FOG LAMP	MTG CRACKED	277.83	277.83
1	LH FOG LAMP COVER	CUT	93.75	93.75
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	763.50	-
1	FRONT LH FENDER INNER SHIELD	SERVICEABLE	222.80	-
10	FRONT LH FENDER INNER SHIELD CLIP @\$2.60	NOT NECESSARY	26.00	-
12	BUMPER CLIP @\$4.50	NECESSARY	54.00	54.00
1	FRONT GRILLE OUTER (ADDITIONAL)	SERVICEABLE	79.30	-
1	FRONT GRILLE INNER (ADDITIONAL)	CRACKED	239.80	239.80
2	FRONT GRILLE MOULDING @\$39.40 (ADDITIONAL)	NECESSARY	78.80	78.80
1	LH HEADLAMP (ADDITIONAL)	MTG CRACKED	1,285.00	1,285.00
	LESS 25% DISCOUNT		-1,121.57	-656.32
			3,364.71	1,968.96
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND LIGHTING.		40.00	15.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMEN AND FRONT LH FENDER .		400.00	200.00
	SPRAY PAINTING ON AFFECTED & REPLACED PARTS.		500.00	200.00
			940.00	415.00
	<b>GRAND TOTAL</b>		<b>4,304.71</b>	<b>2,383.96</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,900.00</b>
---	--	--	-----------------

Report Ref No. CC4/FCI21007602/Kra3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SMN 8397A**

**INSPECTION**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMN 8397A

### RE-INSPECTION





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SMN 8397A**

**RE-INSPECTION**

