

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007606/BGA3Q2**Date:** 14/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070130974
Claimant Vehicle No :	SDZ2878L	Insured Vehicle No :	SMV1018Z
Date of Loss:	11/07/2021	Nature of Claim:	TP
		Claim No:	4600594246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ2878L		
Make & Model:	MITSUBISHI LANCER, 1.6 CVT SPORTS GLX (A)	Engine No:	4G18KA2828
Reg. Date:	16/12/2008 (Man. Year: 2008)	Chassis No:	JMYSTCS3A9U002157
Colour:	Black	Odometer:	283587 km
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,025.23	3,481.10	5,544.13	61.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	1,870.00	2,940.00	61.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,835.23	5,351.10	8,484.13	61.32
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	13,835.23	4,250.00	9,585.23	69.28
+ GST 7.00/7.00% (S\$)	968.47	297.50	670.97	69.28
Nett Amount (S\$)	14,803.70	4,547.50	10,256.20	69.28
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		160.00		
Nett Liability (S\$)		5,254.95		
Global Sum Settlement (S\$)		5,250.00		

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 13/07/2021 Inspected At:

Estimated Period of Repair: 6.0 days

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING
 AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	869.00 FL	*869.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	170.20 FL	*40.00 FL
3	1		*REAR BUMPER LOWER	No such part	358.00 FL	*- FL
4	1		*REAR FENDER RH	Dented	785.00 FL	*785.00 FL
5	1		*REAR FENDER INNER PANEL RH	Not Damaged	520.00 FL	*- FL
6	1		*REAR FENDER INNER COWLING	Not Damaged	95.80 FL	*- FL
7	1		*REAR FENDER INNER TRIM BOARD	Not Damaged	214.60 FL	*- FL
8	1		*REAR FENDER AIR VENTS	Not Damaged	58.00 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING TOP	Not Necessary	48.00 FL	*- FL
10	1		*REAR WINDSCREEN MOULDING BOTTOM	Not Necessary	68.00 FL	*- FL
11	2		*REAR WINDSCREEN MOULDING SIDE	Not Necessary	388.00 FL	*- FL
12	1		*REAR DOOR RH	Dented	768.00 FL	*768.00 FL
13	1		*REAR DOOR OUTER BLACK TAPE RH	Necessary	68.00 FL	*22.00 FL
14	1		*REAR DOOR INNER LOCK RH	Not Damaged	267.50 FL	*- FL
15	1		*REAR DOOR INNER LOCK STICKER RH	Not Damaged	45.00 FL	*- FL
16	1		*REAR DOOR WEATHERSTRIP RH	Not Damaged	126.20 FL	*- FL
17	1		*REAR DOOR INNER TRIM BOARD RH	Not Damaged	312.00 FL	*- FL
18	1		*SIDE SKIRT RH	Cut	487.60 FL	*225.00 FL
19	1		*REAR SHOCK ABSORBER RH	Not Damaged	296.00 FL	*- FL
20	1		*REAR LOWER ARM RH	Dented	233.00 FL	*233.00 FL
21	1		*REAR UPPER ARM RH	Not Damaged	217.00 FL	*- FL
22	1		*REAR CONTROL ARM RH	Not Damaged	372.00 FL	*- FL
23	1		*REAR KNUCKLE ARM RH	Dented	348.00 FL	*348.00 FL
24	1		*REAR KNUCKLE ARM BEARING RH	Jammed	279.80 FL	*189.00 FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*REAR BUMPER LOWER CLIPS	No such part	50.00 FS	*- FS
28	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*REAR WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
33	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	120.00 FS	*- FS
34	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	60.00 FS	*- FS
35	1		*REAR DOOR SEALANT	Not Necessary	100.00 FS	*- FS
36	1		*REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*REAR ALLOY RIM	Dented	980.00 FS	*300.00 FS
39	1		*REAR TYRE	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,764.70	3,829.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	739.47	347.90
Total Parts (\$\$)	9,025.23	3,481.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REVERSE SENSOR	New	100.00	60.00
2	R&R REAR WINDSCREEN	New	250.00	0.00
3	R&R REAR DOOR COMPONENT	New	150.00	0.00
4	R&R REAR UNDER CARRIAGE	New	300.00	120.00
5	R&R REAR TYRE AND BALANCING	New	100.00	0.00
6	WHEEL ALIGNMENT	New	180.00	60.00
7	R&R SIDE SKIRT RH	New	150.00	30.00
8	CHECK WIRING	New	100.00	0.00
9	CONDUCT WATER LEAK TEST	New	180.00	0.00
10	UPHOLSTERY	New	300.00	0.00
11	PANEL BEATING	New	1,400.00	800.00
12	RUST PROOFING	New	200.00	0.00
13	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (\$\$)			4,810.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >