

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21007610/UBA3Q2
Date: 16/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0002585_02
Claimant Vehicle No :	SJY5448J	Insured Vehicle No :	SJK7944D
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0003060

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY5448J		
Make & Model:	HONDA STREAM, 1.8 X (A)	Engine No:	R18A1792665
Reg. Date:	13/09/2010 (Man. Year: 2008)	Chassis No:	RN61083529
Colour:	Black	Odometer:	201504 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,005.60	3,864.32	6,141.28	61.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,400.00	1,400.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,805.60	6,264.32	7,541.28	54.62
Approved Total (Overridden) (S\$)		5,000.00		

Nett Amount (S\$)	13,805.60	5,000.00	8,805.60	63.78
+ Car Rental (5.0 x S\$180.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,907.45		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Zoom Autowerks Pte Ltd (HQ)
 130 Bedok Reservoir Road, Eunos Spring, #08-1339
 Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2021)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY5448J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	786.30 FL	*654.00 FL
2	1		*REAR BUMPER SIDE RETAINER	O/S Bent	98.80 FL	*25.50 FL
3	1		*REAR BUMPER TOW GARNISH	Not Necessary	34.70 FL	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*39.00 FL
5	1		*REAR END PANEL TOP GARNISH	Twisted	195.60 FL	*184.20 FL
6	1		*REAR END PANEL	Badly Dented	645.90 FL	*440.60 FL
7	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
8	1		*REAR TAILGATE	Badly Dented	1,171.30 FL	*987.20 FL
9	1		*REAR TAILGATE INNER TRIMBOARD	Cracked	281.60 FL	*281.60 FL
10	1		*REAR TAILGATE INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*39.00 FL
11	1		*REAR TAILGATE INNER LOCK	Shorted / Jammed	245.90 FL	*145.80 FL
12	1		*REAR TAILGATE INNER HANDLE	Not Necessary	68.40 FL	*- FL
13	1		*REAR TAILGATE CENTRE GARNISH	Not Necessary	361.20 FL	*- FL
14	1		*REAR TAILGATE EMBLEM (STREAM)	Necessary	72.40 FL	*32.80 FL
15	1		*REAR TAILGATE LOGO	Not Necessary	98.40 FL	*- FL
16	2		*REAR TAILGATE DAMPER	Not Necessary	390.40 FL	*- FL
17	1		*REAR TAILGATE WEATHERSTRIP	Twisted	268.50 FL	*182.60 FL
18	1		*REAR TAILLAMPS	O/S Cracked	1,450.80 FL	*390.50 FL
19	1		*REAR TAILLAMPS CLIPS	Not Necessary	32.00 FL	*- FL
20	1		*REAR FENDER INNER TRIMBOARD	O/S Cracked	1,540.80 FL	*384.20 FL
21	1		*REAR FENDER INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
22	1		*SET REVERSE SENSOR	Shorted	304.00 FS	*200.00 FS
23	1		*REVERSE SENSOR HOLDER	No such part	160.00 FL	*- FL
24	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	245.70 FL	*- FL
25	1		*REAR FLOOR PANEL	Repair	1,451.60 FL	*- FL
26	1		*REAR SPARE TYRE HOLDER	Not Necessary	425.80 FL	*- FL
27	1		*REAR EXHAUST CHROME MUFFLER	Not fitted	120.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR EXHAUST END PIPE	Bent / Twisted	785.00 FL	*680.90 FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	108.40 FL	*- FL
30	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
31	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
32	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REAR EXHAUST GUM	Not Necessary	120.00 FS	*- FS
35	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	68.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)**12,261.50****4,757.90****- List Item Discount on L Items 20.00/20.00% (S\$)**

2,255.90

893.58

Total Parts (S\$)**10,005.60****3,864.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	980.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	1,000.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	60.00
5	TO REMOVE & INSTALL REAR FLOOR COMPONENTS ,TRIM & GARNISH	New	150.00	80.00
6	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	150.00	120.00
7	TO RE-POSITION ,DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	80.00
Gross Labour Cost (\$\$)			3,800.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >