

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21007612/AGS3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMN1594T **Insured Vehicle No :** SLN5572S
 Date of Loss: 09/07/2021 Nature of Claim: TP Claim No: MFL2021D0002954

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN1594T**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B5561806
 Reg. Date: 26/07/2019 (Man. Year: 2018) Chassis No: RU11311794
 Colour: Blue Odometer: 80769 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,879.00	5,680.16	4,198.84	42.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,050.00	1,580.00	43.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,509.00	7,730.16	5,778.84	42.78
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	13,509.00	6,100.00	7,409.00	54.84
+ Car Rental (5.0 x S\$107.00/day) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,642.45		

INSPECTION

Date of Assignment: 12/07/2021
 Date Inspected: 12/07/2021 Inspected At: Advance Auto Garage
 10 Kaki Bukit Road 2, #01-21 First East Centre
 Singapore 417868
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1594T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	745.30 F	*745.30 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	66.00 F	*66.00 FL
6	2		*REAR BUMPER REFLECTOR	Cracked	302.00 F	*302.00 FL
7	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
8	1		*REAR END PANEL	Dented	474.10 F	*474.10 FL
9	1		*REAR END PANEL TOP GARNISH	Deformed	188.00 F	*188.00 FL
10	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
11	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	85.50 F	*- FL
12	1		*REAR END PANEL BUZZER	Not Necessary	85.20 F	*- FL
13	2		*TAILLAMP	Cracked	925.20 F	*925.20 FL
14	2		*TAILLAMP LOWER GARNISH	Deformed	390.00 F	*390.00 FL
15	1		*TAILGATE	Distorted	1,100.40 F	*1,100.40 FL
16	1		*TAILGATE LOCK	Damaged	185.40 F	*185.40 FL
17	1		*TAILGATE WEATHERSTRIPE	Cut	189.00 F	*189.00 FL
18	1		*TAILGATE INNER TRIM BOARD	Cracked	285.90 F	*285.90 FL
19	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
20	2		*TAILGATE REFLECTOR	Cut	729.20 F	*729.20 FL
21	1		*TAILGATE GLASS MOULDING	Necessary	112.20 F	*112.20 FL
22	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
23	1		*HONDA LOGO	Not Necessary	38.40 F	*- FL
24	1		*VEZEL WORDING	Necessary	48.50 F	*48.50 FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	650.80 F	*- FL
26	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
27	2		*REAR FENDER INNER SHIELD	Not Necessary	396.20 F	*- FL
28	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
29	2		*REAR FENDER ARC PROTECTOR	Not Necessary	369.40 F	*- FL
30	1		*REAR FENDER ARC PROTECTOR CLIPS	Not Necessary	40.00 FS	*- FS
31	1		*SARE TYRE PANEL TOP COVER	Deformed	306.60 F	*306.60 FL
32	1		*SARE TYRE PANEL UNDERCOVER	Torn	254.90 F	*254.90 FL
33	1		*SARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
34	1		*REAR EXHAUST PIPE	Repair	785.00 F	*- FL
35	1		*REAR EXHAUST MOUNTING	Not Necessary	35.40 F	*- FL
36	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	155.40 F	*- FL
37	1		*TOOL BOX SPONGE	Cracked	285.00 F	*285.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,879.00	6,997.70
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,317.54
Total Parts (\$)	9,879.00	5,680.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	150.00	60.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,630.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >