

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 6305U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REFLECTOR RED	CRACKED	24.00	24.00
1	STICKER REFLECTOR LH	NOT NECESSARY	110.00	-
1	STOP LAMP LED ASSY	BROKEN	1,062.00	1,062.00
1	FLASHER LED ASSY	BROKEN	1,020.00	1,020.00
1	REAR FOG LAMP LED ASSY	BROKEN	363.00	363.00
1	BACK UP LIGHT	BROKEN	228.00	228.00
1	REAR BUMPER NSR	CRACKED	1,170.00	1,170.00
			3,977.00	3,867.00
	LABOUR			
	TO DISMANTLE & REPLACE : - PARTS NOS. 1-7	NOT NECESSARY	3,250.00	-
	TO PERFORM REPAIR WORKS ON: - NSR LAST ACCESS PANE - REAR BUMPER NSR BRACKET - FIBER BODY GLASS - ELECTRICAL WIRING		1,950.00	650.00
	TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS:  - NSR LAST ACCESS PANE - REAR BUMPER NSR BRACKET		650.00	325.00
	- FIBER BODY GLASS SPRAY PAINTING : - REAR BUMPER - NSR LAST PANEL		1,280.00	960.00
			7,130.00	1,935.00
	GRAND TOTAL		11,107.00	5,802.00

RECOMMENDED COST OF REPAIRS		5,802.00

Report Ref No. CS/SMR21007614/R1uf3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

ANG BRYAN TANI

**Automotive Assessor / Investigator**