

ASS. REC. BY:

Steve

CS / 1112100.7615 / EQF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

MFL2021D0003008

Sum Insured:

Excess:

1500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repaire:

14

days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 17272

Yr Regn:

31/1/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C.

2.754

Colour:

White

A/C:

Insured / Std / NI / N

Sp. Reading

49889

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

JTFHT02P300250744

Gen. Cond: Good / Fair / Poor / Bught

Steering: In order / Jammed / Locked / Burnt or

Brakes: In order / Jammed / Locked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

P:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

13/7/21

D.O.A.

14/7/21

Survey held at

EFFICIENT Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

AAV-73K

14/07/21 @ 3.59pm Revert to Ill via Merimen.

15/07/21 @ 6.35pm Derrick informed C/A on LS basis & ex: \$1500 via Merimen.

16/07/21 @ 9.30am Informed wksp C/A on LS basis & ex: \$1500 by email.

Steve finalised LS \$8500, 14 days (Red \$9173.30, 52%)

Date/Time, File, Pass to:



: Prel. Report

12/10 Typist



: Final Report

Date/Time, File Return to:

Days Of Repair:

14

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Inve

(\$



: Weekend

(\$

S + RS, SI

Private

Others

TOTAL

Approved by:

MER-OD

Amount Paid:

8500

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK1727Z

MAKE & MODEL : TOYOTA / HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P200250044

DATE : 14 JUL 2021

CLAIM TYPE : OD CLAIM

D.O.A : 13 JUL 2021

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	COST PRICE	TOTAL PRICE
1	1	FRONT BUMPER / CR		\$ 170.00	\$ 170.00
2	1	FRONT BUMPER GRILLE / CR		\$ 60.00	\$ 60.00
3	2	FRONT BUMPER SIDE RETAINER LH/RH / CR		\$ 55.00	\$ 110.00
4	2	FRONT FOG LAMP COVER LH/RH (CRH) / MIS		\$ 40.00	\$ 80.00
5	1	FRONT BUMPER REINFORCEMENT / DD		\$ 90.00	\$ 90.00
6	1	FRONT BUMPER CENTER BEAM / DD		\$ 45.00	\$ 45.00
7	1	FRONT GRILLE TOP / MIS		\$ 90.00	\$ 90.00
8	1	FRONT GRILLE LOWER / MIS		\$ 120.00	\$ 120.00
9	1	FRONT GRILLE INNER / MIS		\$ 170.00	\$ 170.00
10	2	HEADLAMP ASSY LH/RH / CR CLH (RH)		\$ 750.00	\$ 1,500.00
11	2	HEADLAMP BRACKET LH/RH (CLH) / MIS		\$ 10.00	\$ 20.00
12	1	BONNET / DD		\$ 200.00	\$ 200.00
13	1	BONNET LOCK X		\$ 36.00	\$ 36.00
14	2	BONNET HINGE LH/RH X		\$ 22.00	\$ 44.00
15	1	FRONT CORNER PANEL RH X		\$ 55.00	\$ 55.00
16	1	FRONT SUPPORT PANEL / DD		\$ 140.00	\$ 140.00
17	2	FRONT SUPPORT REINF LOWER LH/RH / DD		\$ 65.00	\$ 130.00
18	2	TOWING COVER / MIS		\$ 12.00	\$ 24.00
19	1	AIR CLEANER BOX ?		\$ 250.00	\$ 250.00
20	1	RADIATOR FAN COWLING ?		\$ 150.00	\$ 150.00
21	1	TOYOTA LOGO / REC		\$ 28.00	\$ 28.00
22	1	FRONT STEP GARNISH RH X		\$ 55.00	\$ 55.00
23	1	RADIATOR ?		\$ 520.00	\$ 520.00
24	1	CONDENSER / DD		\$ 450.00	\$ 450.00
25	1	A/C DISCHARGE HOSE / BT		\$ 120.00	\$ 120.00
26	1	A/C SUCTION HOSE / BT		\$ 250.00	\$ 250.00
27	1	A/C LIQUID PIPE ?		\$ 150.00	\$ 150.00
28	1	INTERCOOLER ?		\$ 440.00	\$ 440.00
29	1	REAR BUMPER / CR		\$ 130.00	\$ 130.00
30	2	REAR BUMPER RETAINER LH/RH / CR		\$ 18.00	\$ 36.00
31	2	REAR BUMPER UPPER COVER LH/RH / CR		\$ 35.00	\$ 70.00
32	2	REAR BUMPER UPPER COVER RETAINER LH/RH / MIS		\$ 15.00	\$ 30.00
33	2	REAR FENDER AIR DUCT LH/RH ?		\$ 20.00	\$ 40.00
34	2	REAR FENDER LH/RH (CLH) / DD		\$ 600.00	\$ 1,200.00
35	2	TAIL LAMP LH/RH / CR		\$ 90.00	\$ 180.00
36	1	TAIL LAMP PANEL LH / DD		\$ 240.00	\$ 240.00
37	1	TAIL LAMP INNER PANEL LH X R		\$ 120.00	\$ 120.00
38	1	EXHAUST SILENCER X		\$ 300.00	\$ 300.00
39	1	END PANEL OUTER / DD		\$ 130.00	\$ 130.00
40	1	TAILGATE / DD		\$ 700.00	\$ 700.00

41	1	TAILGATE LOCK / BT		\$ 100.00	\$ 100.00
42	1	TAILGATE WEATHERSTRIP / TN		\$ 45.00	\$ 45.00
43	2	TAILGATE HINGE LH/RH / BT (LH & RH)		\$ 120.00	\$ 240.00
44	2	TAILGATE STAY LH/RH		\$ 110.00	\$ 220.00
45	1	TAILGATE INNER TRIM BOARD / TN		\$ 150.00	\$ 150.00
46	1	TAILGATE LOGO / nec		\$ 25.00	\$ 25.00
47	1	TAILGATE EMBLEM HIACE / nec		\$ 20.00	\$ 20.00
48	1	REAR WINDSCREEN GLASS / BK		\$ 700.00	\$ 700.00
49	1	REAR FENDER INNER TRIM BOARD LH		\$ 180.00	\$ 180.00
				\$ 8,391.00	\$ 10,353.00

TOTAL PRICE	\$ 10,353.00
PLUS 10%	\$ 1,035.30
SUB TOTAL PRICE	\$ 11,388.30

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET / nec		\$ 50.00	\$ 30 50.00
2	1	FRONT GRILLE CLIPS SET / nec		\$ 50.00	\$ 10 50.00
3	1	TOWING FEE / nec		\$ 70.00	\$ 70.00
4	1	FRONT NO. PLATE / mis		\$ 45.00	\$ 40 45.00
5	1	RADIATOR COOLANT		\$ 50.00	\$ 50.00
6	2	WINDSCREEN SEALANT / nec		\$ 80.00	\$ 40 160.00
7	1	TAILGATE TRIM BOARD CLIPS SET / nec		\$ 50.00	\$ 10 50.00
8	1	REVERSE SENSOR / Shld		\$ 200.00	\$ 200.00
9	1	REAR BUMPER CLIP SET / nec		\$ 50.00	\$ 30 50.00
10	1	PAN PACIFIC METAL PLATE / nec		\$ 80.00	\$ 50 80.00
11	1	70 KM/H STICKER / nec		\$ 30.00	\$ 20 30.00
TOTAL S/NETT				\$ 755.00	\$ 835.00

Labour Charges

1	To cut & weld damaged panels FRONT, LH/RH REAR portions ,To panel beat inner panels,chassis frame members, to remove & replace damaged parts.	\$ 2,400.00	1800
2	To apply anti rust coat and Tuff Kote affected areas.	\$ 200.00	30
3	To check and rectify lighting & wiring harness & replace reverse sensor	\$ 150.00	30
4	To Spray painting for Front, LH/RH REAR portions, & affected areas.	\$ 2,000.00	1600
5	To remove & refit radiator,condenser,other major components,top up A/C gas.	\$ 200.00	80
6	To remove and refit rear windscreen glass.	\$ 150.00	120
7	To do wheel alignment.	\$ 100.00	60
8	To transfer tailgate components to new tailgate.	\$ 100.00	50
9	To remove & refit exhaust system to assist workload.	\$ 150.00	X

TOTAL LABOUR	\$ 5,450.00
Total Cost of Repairs	\$ 17,673.30

(Total parts + Total S/Nett + Total Labour Cost)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) 14/7/21, 11:00am

OD- NA AL
EXCISE - ?

P/P

My Ref S/S
14 days