

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21007625/Vtce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 21/07/2021 SINGAPORE 068811 ATTN: KITTY TEO Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 8194K SKW 8582H Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03DM6 Excess (\$) 0.00 **CHEN XIN YOU Assign Date** 14/07/2021 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA VELLFIRE 2.4Z** Make & Model 2362 c.c HIDDEN 2012 Engine No. Year of Reg. ANH208218671 **BLACK** Chassis No. Colour Odometer 267269 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/40 ZR19 MICHELIN 5 mm 245/40 ZR19 **MICHELIN** L/H Front Tyre 5 mm 245/40 ZR19 **MICHELIN** R/H Rear Tyre 5 mm MICHELIN L/H Rear Tyre 245/40 ZR19 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 12/07/2021 14/07/2021 (12:30 PM) Inspect Date / Time Accident Date **EVERGUM AUTO SERVICES** Survey held at BLK 3022A UBI ROAD 1 #01-51 SINGAPORE 408716 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM21007625/Vtce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days