

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21007627/GUF3E2

**Date:** 16/07/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070005952
<b>Claimant Vehicle No :</b>	SBS6681X	<b>Insured Vehicle No :</b>	SMR7219S
Date of Loss:	11/07/2021	Nature of Claim:	TP
		Claim No:	2785286759SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6681X	Engine No:	902926C1005776
Make & Model:	MERCEDES-BENZ 200E, 2.0 (A)	Chassis No:	WEB62808323125123
Reg. Date:	06/08/2013 (Man. Year: 2013)	Odometer:	649331 km
Colour:	White/Purple		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5(D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	450.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>450.00</b>	<b>450.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>31.50</b>	<b>31.50</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>481.50</b>	<b>481.50</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment:	14/07/2021		
Date Inspected:	14/07/2021	Inspected At:	SBS Transit Ltd (AMK) 15 Ang Mo Kio Street 63 Singapore 569117
Estimated Period of Repair:	1.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

# REPAIR DETAILS

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SUPPLY 3 WORKERS (9 WORKING HOURS)-REPLACE RIGHT SIDE HEADLAMP-REPLACE RIGHT SIDE HEADLAMP COVER-REPAIR LEFT SIDE HEADLAMP COVER-REPAIR FRONT BUMPER-SPRAY PAINTING LEFT & RIGHT SIDE HEADLAMP COVER-SPRAY PAINTING FRONT BUMPER	New	450.00	450.00
<b>Gross Labour Cost (\$\$)</b>			<b>450.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >