

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21007627/GUF3E2

Date: 16/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070005952
Claimant Vehicle No : SBS6681X **Insured Vehicle No :** SMR7219S
Date of Loss: 11/07/2021 Nature of Claim: TP Claim No: 2785286759SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6681X**
Make & Model: MERCEDES-BENZ 200E, 2.0 (A) Engine No: 902926C1005776
Reg. Date: 06/08/2013 (Man. Year: 2013) Chassis No: WEB62808323125123
Colour: White/Purple Odometer: 649331 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70R22.5 Rear Tyre Size: 275/70R22.5(D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	595.00	595.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	634.00	634.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,229.00	1,229.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	86.03	86.03	0.00	0.00
Nett Amount (S\$)	1,315.03	1,315.03	0.00	0.00

INSPECTION

Date of Assignment: 14/07/2021
Date Inspected: 14/07/2021 Inspected At: SBS Transit Ltd (AMK)
15 Ang Mo Kio Street 63
Singapore 569117
Estimated Period of Repair: 1.0 days

Adjuster: XING GUO QIANG

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BLINKER LAMP;FRT RIGHT	Cracked	43.00 F	*43.00 F
2	1		*BUMPERETTE;FRT BUMPERETTE.O/S	Cracked	536.00 F	*536.00 F
3	1		*PURPLE PAINT	Necessary	8.00 F	*8.00 F
4	1		*WHITE PAINT	Necessary	8.00 F	*8.00 F
				Total Parts (S\$)	595.00	595.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY 3 WORKERS (9 WORKING HOURS)-REPLACE RIGHT SIDE HEADLAMP-REPLACE RIGHT SIDE HEADLAMP COVER-REPAIR LEFT SIDE HEADLAMP COVER-REPAIR FRONT BUMPER-SPRAY PAINTING LEFT & RIGHT SIDE HEADLAMP COVER-SPRAY PAINTING FRONT BUMPER (CONTRACTORS REPAIR CHARGES)	New	450.00	450.00
2	(2) WORKSHOP LABOUR	New	184.00	184.00
Gross Labour Cost (\$\$)			634.00	634.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >