

EGI

ASS. REQ. BY:

Steve

CS/EG121007628/EVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: XD 553R

Policy No.

Claims No. CDMCG21001293

Sum Insured:


Excess:

(Client's Record)

Make of Vehl:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Real. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STR 10780

Yr Regn:

9/6/29

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

C.C. 1359

Colour:

White

A/C: Insured / Std / NI / N

Sp. Reading

268894

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

GE 6150165

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brakes: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wet lake.

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

10/1/21

D.O.I.

15/7/21

Survey held at

Autum Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR RM

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Nil - JOK

29/7/21

Steve confirmed LS \$2400 (Red 4070,62%)

File/Time, File, Post 107

☐

: Prel. Report

☐

: Final Report

File/Time, File, Return 107

29/7/21-Typist

Approved/Printed:

Merimen

ump sum / L.P. / C

LS \$2400

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Invs

(\$

☐

: Weekend

(\$

Survey Fee:

Transportation:

\$ + RS \$

Phone

Others

TOTAL

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SJR1078G

Model: Honda Fit

QTY	Description	Repairer's Estimate	
	Spare Parts - List Items		
1	Front bumper ?	\$	800.00
1	Front right fender / 00	\$	800.00
1	Front RH headlight / 00	\$	800.00
1	Top RH panel (p111) / 00	\$	1,000.00
1	Front bonnet X 00	\$	900.00

\$ 4,300.00

c/f: \$

\$ 4,300.00

Special Nett Items**AMT S\$**

\$ -**S/N. Labour Charges**

1	Remove and refit and panel beating	\$	800.00	600
2	Remove, refit and replaced damage and check up rear electrical wiring	\$	150.00	30
3	Remove and refit inner garnishes trim to assist repair	\$	200.00	30
4	To apply undercoating on replaced panel	\$	120.00	30
5	To Respray Painting.	\$	900.00	600

\$ 2,170.00**GRAND TOTAL**

\$ 6,470.00

Steve (LKK)
15/7/21, 10:30am

Wet AL
L/S
My AC by
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: