

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21007632/APS3Q2
Date: 06/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993609
Claimant Vehicle No :	SLB4026Y	Insured Vehicle No :	SKK5218T
Date of Loss:	12/07/2021	Nature of Claim:	TP
		Claim No:	3837517348SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4026Y		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	LEB4228539
Reg. Date:	06/04/2016 (Man. Year: 2015)	Chassis No:	GP71015219
Colour:	White	Odometer:	119004 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,064.88	9,756.32	5,308.56	35.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	3,490.00	730.00	17.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,284.88	13,246.32	6,038.56	31.31
Approved Total (Overridden) (S\$)		10,600.00		

Nett Amount (S\$)	19,284.88	10,600.00	8,684.88	45.03
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		11,536.45		
Global Sum Settlement (S\$)		11,500.00		

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Sin Yu Sin Workshop (HQ)
 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,293.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	135.00 FL	*135.00 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Necessary	76.00 FL	*76.00 FL
4	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	78.00 FL	*78.00 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	85.80 FL	*85.80 FL
6	2		*REAR TAILGATE NO PLATE LAMP L/R	Not Necessary	104.80 FL	*- FL
7	1		*REAR TAILGATE NO PLATE LAMP GARNISH	Cracked	243.00 FL	*243.00 FL
8	1		*REAR TAILGATE NO PLATE TOP CHROME	Not Necessary	480.00 FL	*- FL
9	2		*REAR TAILGATE REFLECTOR LAMP L/R	Cracked	709.60 FL	*709.60 FL
10	2		*REAR TAILGATE HINGE L/R	Not Necessary	133.20 FL	*- FL
11	2		*REAR TAILGATE DAMPER L/R	Not Necessary	330.00 FL	*- FL
12	1		*REAR TAILGATE WEATHERSTRIP	Cut	185.60 FL	*185.60 FL
13	1		*REAR TAILGATE MECHANISM LOCK	Damaged	397.90 FL	*397.90 FL
14	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	39.00 FL	*- FL
15	1		*REAR TAILGATE INNER TRIM	Cracked	435.80 FL	*435.80 FL
16	1		*REAR TAILGATE INNER TRIM HANDLE	Deformed	56.10 FL	*56.10 FL
17	1		*REAR TAILGATE KEYLESS SMART SENSOR	Cracked	256.60 FL	*125.00 FL
18	2		*REAR TAILLAMP L/R	Cut	1,041.00 FL	*1,041.00 FL
19	2		*REAR TAILLAMP LOWER PANEL L/R	Repair	510.00 FL	*- FL
20	1		*REAR BUMPER	Distorted	1,080.60 FL	*989.00 FL
21	2		*REAR BUMPER SIDE REFLECTOR GARNISH L/R	N/S Deformed / O/S Missing	219.60 FL	*219.60 FL
22	2		*REAR BUMPER SIDE REFLECTOR L/R	N/S Cut / O/S Missing	172.80 FL	*172.80 FL
23	2		*REAR BUMPER SIDE SPONGE L/R	Cracked	143.60 FL	*143.60 FL
24	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	110.80 FL	*110.80 FL
25	1		*REAR BUMPER TOWING COVER	Missing	48.00 FL	*48.00 FL
26	1		*REAR BUMPER INNER BUZZER	Damaged	128.00 FL	*83.00 FL
27	1		*REAR BUMPER INNER COVER FINISHER	Not Necessary	38.00 FL	*- FL
28	1		*REAR END PANEL	Distorted	695.00 FL	*695.00 FL
29	1		*REAR END PANEL GARNISH	Deformed	205.80 FL	*205.80 FL
30	1		*REAR SPARE TYRE PANEL TOP BOARD	Deformed	305.80 FL	*305.80 FL
31	1		*REAR SPARE TYRE PANEL TOP TRAY	Deformed	266.40 FL	*266.40 FL
32	1		*REAR SPARE TYRE PANEL TOP SPONGE	Cracked	215.00 FL	*215.00 FL
33	1		*REAR SPARE TYRE PANEL	Buckled	1,089.80 FL	*1,089.80 FL
34	1		*REAR SPARE TYRE PANEL STIFFENER	Not Necessary	186.60 FL	*- FL
35	2		*REAR SUB CHASSIS L/R	Repair	770.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR SUB CHASSIS TOP PANEL L/R	Repair	580.00 FL	*- FL
37	1		*REAR TOWING HOOK BRACKET	Not Necessary	238.00 FL	*- FL
38	2		*REAR FENDER INNER TRIM BOARD L/R	Deformed	1,698.40 FL	*796.00 FL
39	2		*REAR FENDER INNER TRIM TOP COVER L/R	Not Necessary	130.00 FL	*- FL
40	2		*REAR FENDER INNER SHIELD L/R	Torn	220.00 FL	*220.00 FL
41	1		*REAR EXHAUST SILENCER BOX	Repair	776.90 FL	*- FL
42	3		*REAR EXHAUST MOUNTING	Not Necessary	204.00 FL	*- FL
43	1		*REAR EXHAUST HEAT SHIELD	Crumpled	168.00 FL	*168.00 FL
44	1		*HYBRID BATTERY AIR DUCT	Deformed	430.80 FL	*255.00 FL
45	1		*HYBRID BATTERY AIR BLOWER	Not Necessary	268.80 FL	*- FL
46	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
47	1		*REAR TAILGATE INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
48	1		*REAR TAILGATE REVERSE CAMERA	Damaged	400.00 FS	*400.00 FS
49	1		*REAR NO PLATE	Deformed	30.00 FS	*30.00 FS
50	1		*REAR NO PLATE GARNISH	Deformed	50.00 FS	*30.00 FS
51	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
52	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
53	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
54	1		*REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
55	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	30.00 FS	*30.00 FS
56	1		*REAR SPARE TYRE INSULATOR MAT	Necessary	300.00 FS	*200.00 FS
57	2		*REAR FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*30.00 FS
58	2		*REAR FENDER INNER TRIM BOARD CLIP	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,461.10	11,905.40
- List Item Discount on L Items 20.00/20.00% (\$)	3,396.22	2,149.08
Total Parts (\$)	15,064.88	9,756.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	30.00
2	TO TRANSFER TAILGATE MECHANISM AND WIRING ASSY	New	60.00	60.00
3	TO REMOVE ,REFIX REAR TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIX REVERSE CAMERA ASSY	New	100.00	50.00
6	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS ,GARNISHES ,SEATS ,ETC FOR NECESSARY REPAIRS	New	160.00	140.00
7	TO RUSTPROOF AFFECTED AREAS	New	100.00	80.00
8	TO REMOVE ,REPLACE AND REINSTALL REAR EXHAUST SILENCER BOX	New	120.00	80.00
9	TO REMOVE ,REFIX HYBRID BATTERY	New	350.00	280.00
10	TO STRAIGHTEN ,REPAIR ,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,500.00	1,400.00
11	TO SPRAY PAINTING ON AFFECTED AREA	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			4,220.00	3,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >