

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007633/NRS3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509589-04
Claimant Vehicle No :	SMQ3770Y	Insured Vehicle No :	SLN8619Y
Date of Loss:	13/07/2021	Nature of Claim:	TP
		Claim No:	3633360743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ3770Y		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZR0D76107
Reg. Date:	13/11/2019 (Man. Year: 2019)	Chassis No:	MR053REH604597313
Colour:	White	Odometer:	31734 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,624.17	696.50	927.67	57.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	790.00	1,290.00	62.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,704.17	1,486.50	2,217.67	59.87
+ GST 7.00/7.00% (S\$)	259.29	104.06	155.23	59.87

Nett Amount (S\$)	3,963.46	1,590.56	2,372.90	59.87
+ Car Rental (2.0 x S\$107.00/day) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,806.56		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 14/07/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	487.00 FL	*487.00 FL
2	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Serviceable	58.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	395.00 FL	*395.00 FL
4	1		*END PANEL	Repair	650.00 FL	*- FL
5	1		*END PANEL TOP GARNISH	Serviceable	88.90 FL	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
7	1		*SET REVERSE SENSOR	Serviceable	280.00 FS	*- FS
8	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					2,043.90	917.00
- List Item Discount on L Items 25.00/25.00% (S\$)					419.73	220.50
Total Parts (S\$)					1,624.17	696.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REPLACE NEW REVERSE SENSOR AND RESET TO THE SAME	New	80.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISH ,INNER LINING ,INNER TRIM ,CUSHION SEAT ,ETC TO FACILITATE REPAIR	New	200.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT /WELD AND CUT ON THE END PANEL.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE BOOTLID ETC	New	900.00	360.00
4	TO PUTTY AND SPRAY PAINTING ON THE BOOTLID ,REAR BUMPER ,END PANEL	New	750.00	360.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	40.00
Gross Labour Cost (S\$)			2,080.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >