

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007634/NPS3Q2
Date: 12/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447623
Claimant Vehicle No :	SMR7446C	Insured Vehicle No :	SCY9555P
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	5565478865SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR7446C	Engine No:	PE21265507
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A)	Chassis No:	JM6GL1072K0314426
Reg. Date:	20/01/2020 (Man. Year: 2019)	Odometer:	25525 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,362.40	6,399.60	2,962.80	31.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,940.00	1,170.00	37.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,472.40	8,339.60	4,132.80	33.14
+ GST 7.00/7.00% (S\$)	873.07	583.77	289.30	33.14

Nett Amount (S\$)	13,345.47	8,923.37	4,422.10	33.14
+ Car Rental (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,125.37		
Global Sum Settlement (S\$)		10,125.00		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 15/07/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*END PANEL	Dented	701.00 FL	*701.00 FL
2	1		*END PANEL TOP GARNISH	Cracked	149.00 FL	*149.00 FL
3	1		*MAZDA LOGO	Necessary	68.00 FL	*68.00 FL
4	1		*EMBLEM MAZDA 6	Necessary	40.00 FL	*40.00 FL
5	1		*EMBLEM SKYACTIV	Necessary	38.00 FL	*38.00 FL
6	1		*BOOTLID	Dented	1,135.00 FL	*1,135.00 FL
7	1		*BOOTLID WEATHERSTRIP	Deformed	115.00 FL	*115.00 FL
8	2		*BOOTLID HINGE	Serviceable	440.00 FL	*- FL
9	1		*BOOTLID LOCK	Deformed	161.00 FL	*161.00 FL
10	1		*REAR BUMPER	Cracked	1,099.00 FL	*1,099.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	539.00 FL	*539.00 FL
12	1		*REAR UNDER COVER	Serviceable	123.00 FL	*- FL
13	2		*REAR TOW HOOK N/S & O/S	N/S Missing / O/S Deformed	100.00 FL	*100.00 FL
14	1		*REAR BUMPER N/S & O/S REFLECTOR	N/S Cracked / O/S Serviceable	84.00 FL	*42.00 FL
15	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	42.00 FL	*- FL
16	2		*N/S & O/S TAIL LAMP	Deformed	4,006.00 FL	*3,200.00 FL
17	2		*N/S & O/S BOOTLID REFLECTOR	Serviceable	1,948.00 FL	*- FL
18	4		*REVERSE SENSOR (ORIGINAL)	Deformed	720.00 FL	*480.00 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
20	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	28.00 FS	*28.00 FS
21	1		*BOOTLID STICKER PREMIER	Necessary	30.00 FS	*30.00 FS
22	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,664.00	7,973.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,301.60	1,573.40
Total Parts (\$)	9,362.40	6,399.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK LAMP WIRING	New	50.00	30.00
2	TO DISMANTLE AND REPLACE REVERSE SENSOR ,CHECK WIRING	New	80.00	30.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS, INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO CUT/WELD AND HEAT ON THE END PANEL .INCLUDING KNOCK-OUT STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR FLOORBOARD PANEL ,REAR N/S & O/S FENDER ETC	New	1,200.00	900.00
5	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,END PANEL,FLOORBOARD PANEL,BOOTLID,REAR N/S & O/S FENDER	New	1,400.00	900.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	80.00
Gross Labour Cost (S\$)			3,110.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >