

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007636/KPA3Q2**Date:** 13/06/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLC4786G **Insured Vehicle No :** SMX2469M

Date of Loss: 10/07/2021 Nature of Claim: TP Claim No: 5797926869SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC4786G**

Make & Model: TOYOTA SIENTA, 1.5 G CVT (A) Engine No: 2NR8584079

Reg. Date: 16/05/2016 (Man. Year: 2016) Chassis No: NSP1707021683

Colour: Metallic Pearl White Odometer: 143189 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 3 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,040.35	5,036.95	10,003.40	66.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	2,610.00	3,050.00	53.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,700.35	7,646.95	13,053.40	63.06
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	20,700.35	6,100.00	14,600.35	70.53
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 14/07/2021 Inspected At: Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 &
17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR LH	Bent	1,184.50 FL	*1,184.50 FL
2	1	*FRONT DOOR STICKER	Necessary	39.70 FL	*39.70 FL
3	1	*FRONT DOOR WEATHERSTRIP	Serviceable	231.30 FL	*- FL
4	1	*FRONT DOOR INNER STOPPER	Missing	32.90 FL	*32.90 FL
5	12	*FRONT DOOR TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
6	2	*DOOR CENTER PILLAR PROTECTIVE STICKERS (TOP/BOTTOM)	Not Necessary	35.00 FL	*- FL
7	2	*DOOR CENTER PILLAR SAFETY INSTRUCTION STICKERS	Not Necessary	112.40 FL	*- FL
8	1	*DOOR CENTER PILLAR OUTER	Repair	443.00 FL	*- FL
9	1	*SLIDING DOOR LH	Bent	1,145.00 FL	*1,145.00 FL
10	1	*SLIDING DOOR STICKER	Necessary	39.70 FL	*39.70 FL
11	1	*SLIDING DOOR INNER LOCK	Repair	1,092.80 FL	*- FL
12	1	*SLIDING DOOR INNER LOCK HANDLE FRAME	Serviceable	840.00 FL	*- FL
13	1	*SLIDING DOOR LOWER LOCK	*Check	185.00 FL	*- FL
14	1	*SLIDING DOOR WEATHERSTRIP (50%)	Cut	419.25 FS	*279.50 FS
15	1	*SLIDING DOOR PROTECTOR	Dented	113.00 FL	*113.00 FL
16	6	*SLIDING DOOR PROTECTOR CLIPS	Necessary	30.00 FL	*30.00 FL
17	1	*SLIDING DOOR INNER REAR REFLECTIVE STICKER	Necessary	35.00 FL	*35.00 FL
18	1	*SLIDING DOOR LOWER ROLLER	*Check	323.00 FL	*- FL
19	1	*SLIDING DOOR GUIDE MOTOR	*Check	2,696.00 FL	*- FL
20	1	*SLIDING DOOR MOTOR REGULATOR	*Check	185.70 FL	*- FL
21	1	*SLIDING DOOR TRIM BOARD	*Check	655.00 FL	*- FL
22	15	*SLIDING DOOR TRIM BOARD CLIPS	*Check	75.00 FL	*- FL
23	1	*SLIDING DOOR SENSOR WEATHERSTRIP (50%)	Cut	658.20 FS	*438.80 FS
24	1	*SLIDING DOOR GLASS REGULATOR	*Check	189.30 FL	*- FL
25	1	*SLIDING DOOR GLASS REGULATOR MOTOR	*Check	597.60 FL	*- FL
26	1	*SLIDING DOOR RAIL LOWER WEATHERSTRIP (50%)	Cut	168.75 FS	*112.50 FS
27	1	*SLIDING DOOR STEP GARNISH	Mtg Cracked	205.00 FL	*205.00 FL
28	1	*SLIDING DOOR SLIDING MOTOR	Repeated	2,542.10 FL	*- FL
29	1	*SLIDING DOOR HINGE UPPER	Repair	204.00 FL	*- FL
30	1	*SLIDING DOOR HINGE MIDDLE	Repair	180.00 FL	*- FL
31	1	*SLIDING DOOR HINGE LOWER	Repair	312.00 FL	*- FL
32	1	*ROCKER PANEL LH	Repair	560.00 FL	*- FL
33	1	*ROCKER PANEL PROTECTIVE STICKER	Necessary	17.50 FL	*17.50 FL
34	1	*REAR FENDER LH	Bent	1,216.30 FL	*1,216.30 FL
35	1	*REAR FENDER PROTECTOR	Missing	54.20 FL	*54.20 FL
36	2	*REAR FENDER PROTECTOR CLIPS	Necessary	10.00 FL	*10.00 FL
37	1	*REAR WHEEL BEARING	*Check	699.00 FL	*- FL
38	1	*REAR SHOCK ABSORBER	Serviceable	210.00 FL	*- FL
39	1	*REAR BUMPER	Mtg Cracked	507.00 FL	*507.00 FL
40	10	*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
41	1	*REAR BUMPER CORNER RETAINER LH	Distorted	60.40 FL	*60.40 FL
42	1	*REAR BUMPER PROTECTOR LH	Serviceable	155.80 FL	*- FL
43	1	*FRONT DOOR VISOR	Necessary	180.00 FS	*120.00 FS
44	1	*SLIDING DOOR VISOR	Necessary	180.00 FS	*120.00 FS
45	1	*SLIDING DOOR STEP GARNISH TOP SCUFF PLATE	Necessary	280.00 FS	*280.00 FS
46	1	*REAR FENDER GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
47	1	*REAR FENDER GLASS SEALER	Necessary	30.00 FS	*30.00 FS
48	1	*REAR FENDER GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
49	1	*REAR WHEEL RIM	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,368.40	6,219.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,328.05	1,182.05
Total Parts (\$\$)	15,040.35	5,036.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK	New	30.00	20.00
2	TO DISMANTLE /REFIT REAR FENDER GLASS	New	100.00	60.00
3	TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS & TRIMS	New	100.00	60.00
4	TO DISMANTLE /REFIT ROOF LINING	New	150.00	100.00
5	TO DISMANTLE /REFIT 2X DOOR FITTINGS /ANCILLARY ACCESSORIES	New	300.00	120.00
6	TO SUPPLY REAR FENDER, ROCKER PANEL BODY SEALANT	New	100.00	0.00
7	TO RESEAL ROCKER PANEL LOWER CHIP RESISTANT PRIMER	New	80.00	0.00
8	TO DISMANTLE /REPLACE REAR UNDER CARRIAGE TO FACILITATE REPAIR (*Check)	New	160.00	0.00
9	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
10	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	160.00	90.00
11	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FLOOR PANEL ,INNER PANEL,DOOR B PILLAR ,REAR FENDER INNER PANEL ETC.CNT,WELD ROCKER PANEL,REAR FENDER AND PARTS REPLACEMENT	New	1,800.00	1,000.00
12	TO RESPRAY AFFECTED AREAS (2K-PEARL WHITE)(FRONT DOOR ,REAR DOOR ,CENTER PILLAR ,ROCKER PANEL,REAR FENDER ,REAR BUMPER & PETROL COVER)	New	1,650.00	1,100.00
13	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS (*Check)	New	950.00	0.00
Gross Labour Cost (\$\$)			5,660.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >