

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007639/AGS3Q2
Date: 25/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900083458
Claimant Vehicle No :	SMC9820X	Insured Vehicle No :	SMK4708D
Date of Loss:	11/07/2021	Nature of Claim:	TP
		Claim No:	5756318416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9820X	Engine No:	1AZE275205
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK5104016032
Reg. Date:	27/12/2013 (Man. Year: 2013)	Odometer:	124274 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		9,500.00		

(S\$)	0.00	9,500.00	-9,500.00
+ GST 7.00/7.00% (S\$)	0.00	665.00	-665.00
Nett Amount (S\$)	0.00	10,165.00	-10,165.00
+ Car Rental (11.0 x S\$140.00/day) (S\$)		1,540.00	
+ Doc/Search Fee (S\$)		7.45	
Nett Liability (S\$)		11,712.45	
Global Sum Settlement (S\$)		11,500.00	

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 0.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$44,000.00

LTA REIMBURSEMENT VALUE (RV) : \$34,200.00

NETT VALUE : \$9,800.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >